



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNB 7611P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	TAILGATE DETECTOR	NOT NECESSARY	321.00	-
1	REAR BUMPER	DENTED	658.00	525.00
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	350.50	-
2	REAR BUMPER BRACKET @\$114.00	NOT NECESSARY	228.00	-
1	REAR BUMPER LIP	DEFORMED	728.90	417.00
1	REAR END PANEL	NOT NECESSARY	660.20	-
	LESS 20% DISCOUNT		-589.32	-
	LESS 25% DISCOUNT		-	-235.50
			2,357.28	706.50
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR BUMPER CLIPS (SN)	NECESSARY	80.00	30.00
1	REAR REVERSE SENSOR (SN)	SHORTED	250.00	200.00
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	60.00	-
			390.00	230.00
<b><u>LABOUR</u></b>				
	PANEL BEATING ON AFFECTED AREAS .		400.00	200.00
	TO CHECK REAR ELECTRICAL WIRING.	NOT NECESSARY	80.00	-
	TO REMOVE AND RENEW REVERSE SENSOR .		150.00	40.00
	APPLY ANTI RUST ON AFFECTED AREAS .	NOT NECESSARY	200.00	-
	SPRAY PAINTING ON AFFECTED AREAS .		400.00	200.00
			1,230.00	440.00
<b>GRAND TOTAL</b>			<b>3,977.28</b>	<b>1,376.50</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,100.00</b>

Report Ref No. CS/AGI22008028/Gny3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.