

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/ICS22008029/KNY3Q2**Date:** 19/09/2022REFERENCE

Handling Insurer: ECICS Limited Policy No: MCF22A00000100  
**Claimant Vehicle No :** SMX8421K **Insured Vehicle No :** SML5766Z  
 Date of Loss: 30/07/2022 Nature of Claim: TP Claim No: DMCF2200159H.02/SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMX8421K**  
 Make & Model: MERCEDES-BENZ A180, 1.3 SALOON PROGRESSIVE (A) Engine No: 28291480519953  
 Reg. Date: 01/02/2021 (Man. Year: 2020) Chassis No: W1K1771842J283950  
 Colour: Metallic Black Odometer: 31331 km  
 Engine Capacity: 1332 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18  
 Front Left Side: Pirelli 8 mm Rear Left Side: Pirelli 8 mm  
 Front Right Side: Pirelli 8 mm Rear Right Side: Pirelli 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,440.60	1,927.50	2,513.10	56.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,740.00	940.00	1,800.00	65.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>7,180.60</b>	<b>2,867.50</b>	<b>4,313.10</b>	<b>60.07</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>2,300.00</b>		
<b>(\$\$)</b>	7,180.60	2,300.00	4,880.60	67.97
<b>+ GST 7.00/7.00% (\$\$)</b>	502.64	161.00	341.64	67.97
<b>Nett Amount (\$\$)</b>	<b>7,683.24</b>	<b>2,461.00</b>	<b>5,222.24</b>	<b>67.97</b>

INSPECTION

Date of Assignment: 22/08/2022  
 Date Inspected: 22/08/2022 Inspected At: Tong Luck Auto Pte Ltd (HQ)  
 160 Sin Ming Drive, #07-01 Sin Ming AutoCity  
 Singapore 575722  
 Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 19 Sep 2022)

**Parts:** 144 MERCEDES-BENZ A180 1.3 SALOON PROGRESSIVE (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SMX8421K)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR -LH	Bent	1,750.00 FN	*1,750.00 FN
2	1		*FRONT DOOR WEATHERSTRIP -LH	Necessary	328.00 FN	*325.00 FN
3	20		*FRONT DOOR TRIMBOARD RIVETS -LH	Necessary	216.00 FS	*60.00 FS
4	1		*REAR DOOR -LH	Repair	2,048.00 FN	*- FN
5	1		*REAR DOOR WEATHERSTRIP -LH	Serviceable	328.00 FN	*- FN
6	20		*REAR DOOR TRIMBOARD RIVETS -LH	Not Necessary	240.00 FN	*- FN

F=Franchise part. S=SpcNett. N=NettItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,910.00</b>	<b>2,135.00</b>
<b>- Nett Item Discount on N Items 10.00/10.00% (\$\$)</b>	469.40	207.50
<b>Total Parts (\$\$)</b>	<b>4,440.60</b>	<b>1,927.50</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO TRANSFER LH FRONT & REAR DOOR INTERIOR MECHANISM AND GLASS TO NEW DOOR	New	300.00	80.00
2	TO CHECK AND RECTIFY WIRING SYSTEM	New	80.00	20.00
3	TO PANEL BEAT AND STRAIGHTEN LH CENTRE PILLAR ,LH ROCKER PANEL,INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY TO REFIT AND ADJUST THE SAME	New	1,000.00	400.00
4	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS	New	1,200.00	440.00
5	TO APPLY RUST-PROOFING ON REPLACED AND REPAIRED PANELS	New	160.00	0.00
<b>Gross Labour Cost (\$)</b>			<b>2,740.00</b>	<b>940.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >