

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG22008034/ACY3Q2**Date:** 03/11/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210045610
Claimant Vehicle No :	SLZ3734S	Insured Vehicle No :	GBB4931C
Date of Loss:	14/08/2022	Nature of Claim:	TP
		Claim No:	4886365026SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ3734S	Engine No:	3A92UGR9380
Make & Model:	MITSUBISHI ATTRAGE, 1.2 (A)	Chassis No:	MMBSTA13AJH001745
Reg. Date:	30/04/2018 (Man. Year: 2018)	Odometer:	34069 km
Colour:	Silver		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,191.60	3,294.90	6,896.70	67.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,800.00	1,250.00	3,550.00	73.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,991.60	4,544.90	10,446.70	69.68
Approved Total (Overridden) (S\$)		3,600.00		
Nett Amount (S\$)	14,991.60	3,600.00	11,391.60	75.99

INSPECTION

Date of Assignment:	22/08/2022		BLK 1 KAKI BUKIT AVENUE 6
Date Inspected:	22/08/2022	Inspected At:	#01-08 AUTOBAY @ KAKI BUKIT
			SINGAPORE 417883
			Repairer:TSL Auto Garage
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,120.00 FL	*706.00 FL
2	1		*FRONT BUMPER SIDE RETAINER	O/S Damaged	119.00 FL	*45.00 FL
3	1		*FRONT BUMPER FOG LAMP RH	Cracked	330.00 FL	*268.00 FL
4	1		*FRONT BUMPER FOG LAMP COVER RH	Missing	190.00 FL	*190.00 FL
5	1		*FRONT BUMPER LOWER SKIRITNG	Deformed	711.00 FS	*480.00 FS
6	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	390.00 FL	*- FL
7	1		*FRONT BUMPER SPONGE	Not Necessary	190.00 FL	*- FL
8	1		*FRONT HEADLAMP RH	Cracked	690.00 FL	*690.00 FL
9	1		*FRONT HEADLAMP LOWER BRACKET RH	Not Necessary	100.00 FL	*- FL
10	1		*FRONT SUPPORT PANEL	Not Necessary	890.00 FL	*- FL
11	1		*FRONT HEADLAMP PANEL RH	Not Necessary	320.00 FL	*- FL
12	1		*FRONT FENDER RH	Dented	390.00 FL	*390.00 FL
13	1		*FRONT FENDER INNER SHIELD RH	Torn	295.00 FL	*162.00 FL
14	1		*FRONT FENDER EMBLEM RH	Necessary	110.00 FL	*110.00 FL
15	1		*FRONT BONNET	Not Necessary	890.00 FL	*- FL
16	1		*FRONT BONNET HINGE RH	Not Necessary	120.00 FL	*- FL
17	1		*FRONT SPORT RIMS RH	Cut	891.00 FS	*450.00 FS
18	1		*FRONT LOWER ARM RH	Not Necessary	390.00 FL	*- FL
19	1		*FRONT WHEEL HUB RH	Not Necessary	520.00 FL	*- FL
20	1		*FRONT WHEEL HUB BEARING RH	Not Necessary	320.00 FL	*- FL
21	1		*FRONT WHEEL HUB KNUCKLE RH	Not Necessary	490.00 FL	*- FL
22	1		*FRONT STEERING ROD RH	Not Necessary	190.00 FL	*- FL
23	1		*FRONT STEERING SHAFT RH	Not Necessary	490.00 FL	*- FL
24	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
25	1		*FRONT FENDER INNER SHIELD CLIPS	Necessary	50.00 FS	*30.00 FS
26	1		*FRONT TYRE RH	Not Necessary	400.00 FS	*- FS
27	1		*FRONT BUMPER LOWER SKIRTING -SIDE	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,046.00	3,551.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	854.40	256.10
Total Parts (\$\$)	10,191.60	3,294.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO STRAIGHTEN AND PANEL BEAT FRONT FRAME MEMBERS ,TO CUT /WELD AND REMOVE AND REFIT ABOVE PARTS	New	2,000.00	500.00
2	TO PUTTY ,RESPRAY PAINTING AND POLISH FRONT AFFECTED AREAS	New	2,000.00	600.00
3	TO RUST PROOF AFFECTED AREAS	New	100.00	40.00
4	TO CHECK AND RECTIFY WIRING	New	100.00	30.00
5	TO REMOVE AND REFIT FRONT UNDERCARRIAGE ASSY	New	300.00	0.00
6	TO CONDUCT WHEEL ALIGNMENT	New	100.00	80.00
7	TO CONDUCT DIAGNOSTIC SYSTEMS AND TO CLEAR FAULTS CODE	New	200.00	0.00
Gross Labour Cost (\$\$)			4,800.00	1,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >