



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |                                    |                 |   |  |
|--|------------------------------------|-----------------|---|--|
| SOMPO INSURANCE SINGAPORE PL<br>50 RAFFLES PLACE #03-03<br>SINGAPORE LAND TOWERSINGAPORE 048623  |                                    |                 | Ref: CS/SMO22008036/Avy3m4<br>Date: 23/03/2023<br>Code: SMO |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>  |                                    |                 |   |  |
| Insured Veh.   | GBD 9082J                          | Veh. Inspected  | SLB 3779P   |  |
| Policy No.   |                                    | Coverage (\$)   | 0.00  |  |
| Claim No.  | CMTD2202867/GPL                    | Excess (\$)     | 0.00  |  |
| Assign From  | MELVIN YE                          | Assign Date     | 22/08/2022  |  |
| <b>2. Vehicle Particulars &amp; Condition</b>  |                                    |                 |   |  |
| Make & Model   | TOYOTA AXIO                        | c.c             | 1496  |  |
| Engine No.   | HIDDEN                             | Year of Reg.    | 2016  |  |
| Chassis No.  | NRE1610010430                      | Colour          | BRONZE  |  |
| Odometer   | 343395 KM                          | Steering        | IN ORDER  |  |
| Brakes   | IN ORDER                           | Modification    | NIL   |  |
| General  | GOOD                               |                 |   |  |
| <b>3. Conditions of Tyres</b>  |                                    |                 |   |  |
|  | Size                               | Make            | Balance   |  |
| R/H Front Tyre   | 185/60R15                          | WANLI           | 6 mm  |  |
| L/H Front Tyre   | 185/60R15                          | WANLI           | 6 mm  |  |
| R/H Rear Tyre  | 185/60R15                          | WANLI           | 6 mm  |  |
| L/H Rear Tyre  | 185/60R15                          | WANLI           | 6 mm  |  |
| <b>4. Description of Damages</b>   |                                    |                 |   |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.<br>DAMAGES SEE DETAILS.  |                                    |                 |   |  |
| <b>5. General Information</b>  |                                    |                 |   |  |
| Accident Date  | 20/08/2022                         | Inspection Date | 22/08/2022  |  |
| Survey held at   | NO. 4 JALAN BESUT SINGAPORE 619557 |                 |   |  |
| Repairer   | LION CITY RENTALS PTE LTD          |                 |   |  |
| <b>5a. Remarks</b>   |                                    |                 |   |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                    |                 |   |  |
| <b>5b. Estimate Days of Repair</b>   |                                    |                 |   |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:  |                                    |                 | 4 Working Days  |  |