

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22008037/KCY3Q2**Date:** 14/09/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNW00011252200

Claimant Vehicle No : SJV294J **Insured Vehicle No :** SNF9637G

Date of Loss: 08/07/2022 Nature of Claim: TP Claim No: SNM22D205821/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJV294J**

Make & Model: MERCEDES-BENZ E200 (R17), 2.0 (A) Engine No: 27492030068817

Reg. Date: 22/07/2013 (Man. Year: 2013) Chassis No: WDD2120342A815315

Colour: Metallic Brown Odometer: 136329 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45Z R17 Rear Tyre Size: 245/45Z R17

Front Left Side: Michelin 8 mm Rear Left Side: Michelin 8 mm

Front Right Side: Michelin 8 mm Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-------------------|-------------------|-------------------|---------------|
| Parts | 3,307.00 | 1,680.30 | 1,626.70 | 49.19 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,600.00 | 530.00 | 1,070.00 | 66.88 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (\$\$) | 4,907.00 | 2,210.30 | 2,696.70 | 54.96 |
| Approved Total (Overridden) (\$\$) | | 1,750.00 | | |
| Nett Amount (\$\$) | 4,907.00 | 1,750.00 | 3,157.00 | 64.34 |

INSPECTION

Date of Assignment: 22/08/2022

Date Inspected: 24/08/2022 Inspected At: Jin Huat & Co (HQ)
176 SIN MING DRIVE #05-01, SIN MING
AUTOCARE
Singapore 575721

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Sep 2022)

Parts: 143 MERCEDES-BENZ E200 (R17) 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJV294J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---------------------------------|-------------|------------|--------------|
| 1 | 1 | | *REAR BUMPER | Bent | 1,405.00 F | *1,405.00 FL |
| 2 | 1 | | *REAR BUMPER LOWER SPOILER /LIP | Dented | 252.00 F | *252.00 FL |
| 3 | 1 | | *REAR BUMPER REINFORCEMENT | Repair | 828.00 F | *- FL |
| 4 | 1 | | *LH T/LAMP | Serviceable | 612.00 F | *- FL |
| 5 | 1 | | *LH BUMPER SENSOR | Missing | 210.00 F | *210.00 FL |

F=Franchise part. L=ListItemDisc.

| | | |
|---|-----------------|-----------------|
| Sub Total (\$\$) | 3,307.00 | 1,867.00 |
| - List Item Discount on L Items 0.00/10.00% (\$\$) | 0.00 | 186.70 |
| Total Parts (\$\$) | 3,307.00 | 1,680.30 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------------------------|--|----------|-----------------|---------------|
| Labour Items | | | | |
| 1 | REPAIR T/LAMP PANEL ,INNER SUPPORT AND REPLACE PARTS | New | 850.00 | 250.00 |
| 2 | SPRAY PAINTING | New | 750.00 | 280.00 |
| Gross Labour Cost (\$) | | | 1,600.00 | 530.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >