9/21/22, 12:13 PM Adjuster Report

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI22008038/AQY3Q2

21/09/2022 Date:

**REFERENCE** 

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMPCSNA00004942201

**Claimant Vehicle** 

**SLR3186R** 

Insured

SJB2124J

No:

Vehicle No:

Date of Loss:

11/08/2022

Nature of Claim: TP

Claim No:

SNM22D205634/C02/LEWLC

Yes

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

**SLR3186R** Reg No:

Make & Model: HONDA SHUTTLE, 1.5 G CVT (A) Engine No: L15B5004228 Reg. Date: 10/08/2017 (Man. Year: 2017) Chassis No: GK81103596 Colour: White Odometer: 159528 km

**Engine Capacity:** 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable):

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes Nο

**CONDITION OF TYRES** 

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15 Front Left Side: Rear Left Side: Kumho 6 mm Kumho 6 mm Front Right Side: Kumho 6 mm Rear Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,177.20	2,762.80	2,414.40	46.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,080.00	530.00	550.00	50.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,257.20	3,292.80	2,964.40	47.38
Approved Total (Overridden) (S\$)		2,600.00		
Nett Amount (S\$)	6,257.20	2,600.00	3,657.20	58.45

**INSPECTION** 

Date Inspected:

Date of Assignment: 22/08/2022

> 1 Kaki Bukit Ave 6 #01-82 AutoBay 23/08/2022 Inspected At:

Singapore 417883

Repairer: Sin Yu Sin Workshop (HQ)

Estimated Period of Repair: 3.0 days

Adjuster: **ADRIAN LING** Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

9/21/22, 12:13 PM Adjuster Report

### **REPAIR DETAILS**

### Reference

Part Source: (Last Synchronised: 21 Sep 2022)

Parts: N/A HONDA SHUTTLE 1.5 G CVT (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SLR3186R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT GRILLE	Cracked	235.00 FL	*235.00 FL
2	1		*FRONT GRILLE TOP CHROME	Not Necessary	240.00 FL	*- FL
3	1		*FRONT GRILLE LOGO EMBLEM	Necessary	68.00 FL	*68.00 FL
4	1		*FRONT GRILLE LOGO BASE	Not Necessary	96.00 FL	*- FL
5	1		*FRONT BUMPER	Deformed	1,180.00 FL	*985.00 FL
6	1		*FRONT BUMPER TOWING COVER	Not Necessary	38.00 FL	*- FL
7	2		*FRONT BUMPER SIDE RETAINER L/R	Not Necessary	76.00 FL	*- FL
8	1		*FRONT BUMPER REINFORCEMENT BEAM	Dented	380.00 FL	*380.00 FL
9	1		*FRONT HEADLAMP L/R	O/S Cracked	3,360.00 FL	*1,680.00 FL
10	1		*FRONT HEADLAMP LOWER BRACKET L/R	O/S Cracked	136.00 FL	*68.00 FL
11	1		*FRONT PARKING SENSOR	Not Necessary	350.00 FS	*-FS
12	1		*FRONT BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
13	1		*FRONT NO PLATE (ACRYLIC)	Not Necessary	150.00 FS	*- FS
F=Fra	anchise	part. S=SpcN	lett. L=ListItemDisc.			
				Sub Total (S\$)	6,339.00	3,446.00
			- List Item Discount on L Items	20.00/20.00% (S\$)	1,161.80	683.20
				Total Parts (S\$)	5,177.20	2,762.80
				_		

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO CHECK WIRING	New	80.00	30.00
2	TO STRAIGHTEN ,REPAIR ,REALIGN ON REAR AFFECTED AREA AND REPLACE DAMAGED PARTS	New	500.00	300.00
3	TO SPRAY PAINTING ON AFFECTED AREA	New	500.00	200.00
	Gross Labour Cost (S\$)		1,080.00	530.00
Report was unsubmitted during this print-out.				

< END OF ESTIMATES >