

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22008039/KCY3Q2**Date:** 14/09/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNA00012762200

Claimant Vehicle No : SNF9894E **Insured Vehicle No :** SND9683H

Date of Loss: 18/08/2022 Nature of Claim: TP Claim No: SNM22D205830/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNF9894E**

Make & Model: TOYOTA ALPHARD, 2.4 (A) Engine No: 2ARH654980

Reg. Date: 05/02/2016 (Man. Year: 2015) Chassis No: AGH300046539

Colour: Metallic Black Odometer: 33494 km

Engine Capacity: 2493 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50 R18 Rear Tyre Size: 235/50 R18

Front Left Side: Toyo 7 mm Rear Left Side: Toyo 5 mm

Front Right Side: Toyo 7 mm Rear Right Side: Toyo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,251.12	3,966.00	1,285.12	24.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,400.00	1,590.00	810.00	33.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,651.12	5,556.00	2,095.12	27.38
Approved Total (Overridden) (\$\$)		4,400.00		
Nett Amount (\$\$)	7,651.12	4,400.00	3,251.12	42.49

INSPECTION

Date of Assignment: 22/08/2022

Date Inspected: 23/08/2022 Inspected At: Rc Auto-160 Sin Ming (HQ)
160 SIN MING DRIVE, #06-20 SIN MING
AUTOCITY
Singapore 575722

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Sep 2022)
Parts:	M1-MPV	TOYOTA ALPHARD 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNF9894E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent / Cracked	1,853.20 FL	*1,217.00 FL
2	1		*REAR LAMP	Cut	712.60 FL	*575.50 FL
3	1		*REAR CORNER PANEL	Buckled	314.00 FL	*314.00 FL
4	1		*REAR FENDER	Bent	1,643.60 FL	*1,521.00 FL
5	1		*REAR BUMPER RETAINER	Cracked	111.80 FL	*111.80 FL
6	1		*REAR BUMPER REFLECTOR	Cracked	98.70 FL	*98.70 FL
7	1		*REAR BLOWER MOTOR ASSY	Housing Cracked	1,830.00 FL	*1,450.00 FL
					Sub Total (\$\$)	6,563.90
					- List Item Discount on L Items 20.00/25.00% (\$\$)	1,312.78
					Total Parts (\$\$)	5,251.12
						3,966.00

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FEES	New	60.00	50.00
2	TO REMOVE SEATS ,REAR FENDER INNER GARNISH ,CARPETS TO FACILITATE REPAIR	New	150.00	120.00
3	TO RESPRAY AFFECTED PARTS	New	800.00	600.00
4	VACUMM AND TOP UP GAS	New	40.00	40.00
5	TO RENEW ABOVE PARTS	New	1,200.00	700.00
6	TO REMOVE REAR FENDER GLASS	New	150.00	80.00
Gross Labour Cost (\$)			2,400.00	1,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >