

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS/AIS22008042/KVY3Q2**Date:** 19/09/2022**REFERENCE**

Insured/Claimant:	RAVIN PERIASAMY	Policy No:	SP2000683922	
Date of Loss:	16/08/2022	Nature of Claim:	OD	Claim No: 202222006179SL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ4610T	Engine No:	FB16Y442247
Make & Model:	SUBARU XV, 1.6 I-S AWD CVT (A)	Chassis No:	JF1GP3KC5HG200531
Reg. Date:	13/12/2016 (Man. Year: 2016)	Odometer:	88462 km
Colour:	Metallic Dark Blue		
Engine Capacity:	1600 cc		
Market Value/New Car Price:	S\$67,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,155.60	5,349.30	806.30	13.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,930.00	1,570.00	360.00	18.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,085.60	6,919.30	1,166.30	14.42
Approved Total (Overridden) (S\$)		5,500.00		
- Excess (S\$)	0.00	600.00	-600.00	
(S\$)	8,085.60	4,900.00	3,185.60	39.40
+ GST 0.00/7.00% (S\$)	0.00	343.00	-343.00	
Nett Amount (S\$)	8,085.60	5,243.00	2,842.60	35.16

INSPECTION

Date of Assignment:	22/08/2022 Present Location:	Chew Goon Motor (AMK)
		Chew Goon Motor (AMK)
Date Inspected:	23/08/2022 Inspected At:	Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint
		Singapore 568047
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Sep 2022)
Parts:	144	SUBARU XV 1.6 I-S AWD CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLJ4610T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Bonnet (WCP)	Bent	540.00 F	*540.00 F
2	1		*Bonnet Hinges (WCP)	O/S Distorted	72.00 F	*36.00 F
3	1		*Bonnet Lock (WCP)	Repair	90.00 F	*- F
4	1		*Grille (WCP)	Cracked	110.00 F	*110.00 F
5	1		*Grille Emblem (WCP)	Necessary	85.00 F	*85.00 F
6	1		*Grille Chrome Surround Moulding (WCP)	Dented	220.00 F	*220.00 F
7	1		*Grille Top Chrome (WCP)	Dented	160.00 F	*160.00 F
8	1		*Grille Bracket Base (WCP)	Cracked	85.00 F	*85.00 F
9	2		*Headlamps (WCP)	Mtg Cracked	960.00 F	*960.00 F
10	2		*Headlamp Side Brackets (WCP)	Cracked	50.00 F	*50.00 F
11	1		*Front Bumper (WCP)	Cracked	300.00 F	*300.00 F
12	16		*Front Bumper Clips (WCP)	Necessary	24.00 F	*24.00 F
13	1		*Front Bumper Bracket RH (WCP)	Repair	17.00 F	*- F
14	1		*Front Bumper Sponge (WCP)	Cracked	50.00 F	*50.00 F
15	1		*Front Bumper Top Beam (WCP)	Bent	170.00 F	*170.00 F
16	2		*Front Bumper Top Retainers (WCP)	Serviceable	20.00 F	*- F
17	1		*Front Bumper Reinforcement (WCP)	Bent	270.00 F	*270.00 F
18	1		*Front Bumper Tow Point Cover (WCP)	Dented	10.00 F	*10.00 F
19	1		*Front Bumper Lower Core (WCP)	Serviceable	150.00 F	*- F
20	1		*Support Panel (WCP)	Bent	520.00 F	*520.00 F
21	2		*Support Panel Side Sponges (WCP)	Necessary	68.00 F	*68.00 F
22	1		*Radiator (WCP)	Mtg Broken	820.00 F	*600.00 F
23	1		*Air Con Condenser (WCP)	Bent	720.00 F	*520.00 F
24	1		*Air Cleaner Cold Air Intake Duct (WCP)	Cracked	85.00 F	*85.00 F

F=Franchise part.

Sub Total (\$\$)	5,596.00	4,863.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	559.60	486.30
Total Parts (\$\$)	6,155.60	5,349.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To Conduct Electrical Check, Focus Headlamp	New	30.00	20.00
2	To Remove / Refit Air Con Condenser & Refill Air Con Gas	New	100.00	100.00
3	To Remove / Refit, Radiator System, Bleed, Refill Coolant	New	50.00	50.00
4	Labour Charge - Panel Beating, Repairing of Front Chassis, Front O/S Fender, Cnt, Weld Support Panel & Part Replacement	Repair	800.00	600.00
5	To Respray Affected Areas	Repair	950.00	800.00
Gross Labour Cost (\$\$)			1,930.00	1,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >