



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SND 1926K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED	1,790.00	581.00
1	FRONT BUMPER SIDE RETAINER RH	DAMAGED	110.00	110.00
1	FRONT FOG LAMP RH	NOT NECESSARY	320.00	-
1	FRONT FOG LAMP GARNISH RH	DEFORMED	195.00	195.00
1	FRONT BUMPER LOWER CENTER GRILLE	NOT NECESSARY	890.00	-
1	FRONT GRILLE	NOT NECESSARY	820.00	-
1	FRONT GRILLE EMBLEM C/W RADAR	NOT NECESSARY	1,190.00	-
1	FRONT GRILLE CHROME RH	NOT NECESSARY	210.00	-
1	FRONT BUMPER SPONGE	CRACKED	185.00	185.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	330.00	-
1	FRONT HEADLAMP RH (HID - DAYLIGHT)	CUT	3,210.00	3,210.00
1	FRONT HEADLAMP LOWER BRACKET RH	NOT NECESSARY	110.00	-
1	FRONT HEADLAMP PANEL RH	NOT NECESSARY	295.00	-
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	490.00	-
1	FRONT FENDER INNER SHIELD RH	NOT NECESSARY	220.00	-
1	FRONT LOWER ARM RH	NOT NECESSARY	390.00	-
1	FRONT WHEEL HUB RH	NOT NECESSARY	480.00	-
1	FRONT WHEEL HUB BEARING RH	NOT NECESSARY	330.00	-
1	FRONT WHEEL HUB KNUCKLE RH	NOT NECESSARY	590.00	-
	LESS 25% DISCOUNT		-3,038.75	-1,070.25
			9,116.25	3,210.75
1	FRONT SPOT RIMS RH (ORIGINAL) (SN)	CUT	1,790.00	680.00
	LESS 25% DISCOUNT		-447.50	-
			1,342.50	680.00
	<u>SPECIAL NETT ITEMS</u>			
10	FRONT BUMPER CLIPS (SN)	NECESSARY	60.00	30.00
1	SET FRONT TYRE RH (SN)	NOT NECESSARY	500.00	-
10	FRONT FENDER INNER SHIELD CLIPS RH (SN)	NOT NECESSARY	50.00	-

Report Ref No. CS/SMO22008044/Any3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
10	FRONT BUMPER LOWER CENTER GRILLE CLIPS (SN)	NOT NECESSARY	50.00	-
			660.00	30.00
	LABOUR			
	KNOCKING ADJUST FRONT ON AFFECTED AREA. INCLUSIVE OF THE REPAIR OF FRONT FENDER RH.		1,400.00	300.00
	TO PUTTY, RE-SPRAY PAINTING AND POLISH FRONT AFFECTED AREAS.		1,400.00	400.00
	TO RUST PROOF AFFECTED FRONT AREAS.		100.00	30.00
	TO CHECK AND RECTIFY WIRING.		100.00	30.00
	TO REPLACE REVERSE SENSOR AND CHECK.	NOT NECESSARY	100.00	-
	TO REMOVE AND REFIT UNDER CARRIAGE ASSY.	NOT NECESSARY	300.00	-
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	150.00	-
	TO CONDUCT DIAGNOSTIC SYSTEM AND TO CLEAR FAULTS CODE.	NOT NECESSARY	300.00	-
			3,850.00	760.00
GRAND TOTAL			14,968.75	4,680.75
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,700.00

Report Ref No. CS/SMO22008044/Any3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.