

LEANG AUTOMOTIVE

Estimate

Contact : Mr.Ng 9028 6516
Blk 1 Kaki Bukit Ave 6 @ Autobay #01-68
Singapore 417883

TP Seng
Xiao Chen.

YEAR : 2021 VEHICLE NO : SND1926K
MODEL : TOYOTA COROLLA ALTIS ELEGANCE CHASSIS NO : MR2BE3BE500017034

No	Parts	No	Price
1	FRONT BUMPER <i>Debonded</i>	1	\$1,790.00 58/
2	FRONT BUMPER SIDE RETAINER RH <i>2nd.</i>	1	\$110.00 ✓
3	FRONT FOG LAMP RH <i>He ne</i>	1	\$320.00 x.
4	FRONT FOG LAMP GARNISH RH <i>Debonded</i>	1	\$195.00 ✓
5	FRONT BUMPER LOWER CENTER GRILLE <i>new</i>	1	\$890.00 x
6	FRONT GRILLE <i>He ne</i>	1	\$820.00 x
7	FRONT GRILLE EMBLEM C/W RADAR <i>He ne</i>	1	\$1,190.00 x
8	FRONT GRILLE CHROME RH <i>He ne</i>	1	\$210.00 x.
9	FRONT BUMPER SPONGE <i>archd</i>	1	\$185.00 ✓
10	FRONT BUMPER REINFORCEMENT <i>new</i>	1	\$330.00 x
11	FRONT HEADLAMP RH (HID - DAYLIGHT) <i>at.</i>	1	\$3,210.00 ✓
12	FRONT HEADLAMP LOWER BRACKET RH <i>new</i>	1	\$110.00 x
13	FRONT HEADLAMP PANEL RH <i>He ne</i>	1	\$295.00 x.
14	FRONT FENDER RH <i>Repis</i>	1	\$490.00 x.
15	FRONT FENDER INNER SHIELD RH <i>He ne</i>	1	\$220.00 x.
16	FRONT SPOT RIMS RH (ORINIGAL) <i>at.</i>	1	\$1,790.00 680(SN).
17	FRONT LOWER ARM RH <i>2</i>	1	\$390.00 x
18	FRONT WHEEL HUB RH <i>Not</i>	1	\$480.00 x
19	FRONT WHEEL HUB BEARING RH <i>new</i>	1	\$330.00 x
20	FRONT WHEEL HUB KNUCKLE RH	1	\$590.00 x.

\$13,945.00

Discount 25%

\$3,486.25

TOTAL :

\$10,458.75

No	S/N Item	No	Price
1	FRONT BUMPER CLIPS <i>new</i>	10	\$60.00 30
2	FRONT TYRE RH <i>He ne</i>	1SET	\$500.00 x
3	FRONT FENDER INNER SHIELD CLIPS RH <i>3 new</i>	10	\$50.00 x
4	FRONT BUMPER LOWER CENTER GRILLE CLIPS <i>new</i>	10	\$50.00 x.

\$660.00

Parts Total :

\$10,458.75

S/P Item :

\$660.00

TOTAL :

\$11,118.75

30

LEANG AUTOMOTIVE

Estimate

Contact : Mr.Ng 9028 6516
Blk 1 Kaki Bukit Ave 6 @ Autobay #01-68
Singapore 417883

NO	LABOUR	AMOUNT
1	Knocking adjust front on affected area.	\$ 1,400.00 <i>300</i>
2	To putty, re-spray painting and polish front affected areas.	\$ 1,400.00 <i>400</i>
3	To rust proof affected front areas.	\$ 100.00 <i>30</i>
4	To check and rectify wiring.	\$ 100.00 <i>30</i>
5	To replace reverse sensor and check.	\$ 100.00 <i>X</i>
6	To remove and refit under carriage assy.	\$ 300.00 <i>X</i>
7	To conduct wheel alignment.	\$ 150.00 <i>X</i>
8	To conduct diagnostic system and to clear faults code.	\$ 300.00 <i>X</i>

760

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL	:	\$	3,850.00
PARTS TOTAL	:	\$	11,118.75
GRAND TOTAL	:	\$	14,968.75

total: 14680.75

C/S: 3.7K.

02 Days