UCON MOTOR APPRAISER PTE LTD

Motor Appraiser and Insurance Loss Adjustor Blk 361 Yung An Road #12-105 Singapore 610361 Mobile: +65 9232 0012 Email: iconappraiser@gmail.com UEN.: 202006885Z

INSPECTION REPORT

To

ANIMAL ARTS ACADEMY PTE LTD

: 20220923/00164/CCE

Date

: 23 Sep 2022

REFERENCE

Assign by

: ANIMAL ARTS ACADEMY PTE LTD

3rd party Veh.

: GBA6745R

Inspection on Accident on

: 22 Aug 2022 : 18 Aug 2022

Workshop name

: Cheng Chuan Enterprise Pte Ltd

Inspection at

: 2 Kaki Bukit Avenue 2 #02-20/26/30/31

Kaki Bukit Autohub

Singapore 417921

PARTICULARS OF DAMAGED VEHICLE

Registration no.

GBD6085X

Odometer

: 185007 km

Make / Model

NISSAN NV200 DX 1.6 AT

Chassis no.

: VM20058735

Regn. date

Engine no.

: HR16004489D

: 2015

Body colour

: Grey

Engine cap.

: 1597 cc

PRE-ACCIDENT CONDITION OF VEHICLE (STATIC CHECK ONLY)

Steering

: In order

Paintwork

: Fair

Footbrake

: In order

Undercarriage

: Serviceable

Handbrake

In order

Gen. condition

: Fair

TYRE CONDITION ON VEHICLE


	Make		Size	Tread depth	Type of road wheel		
Front N/S	:	Rotalla	175/70R14	70%	Steel		
Front O/S	:	Rotalla	175/70R14	70%	Steel		
Rear N/S	:	Rotalla	175/70R14	70%	Steel		
Rear O/S	:	Rotalla	175/70R14	70%	Steel		

NOTE: Tread depth percentages represents the visually estimated remaining life of tyre treads.

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

20220923/00164/CCE

The damages was found on the rear portion.



RECOMMENDATION

The estimated cost of repair submitted by the repairer <u>Cheng Chuan Enterprise Pte Ltd</u> as per schedule attached has been revised and scrutinised, and in our opinion, we consider it to be fair and reasonable. The repairer have agreed to undertake the repairs at our recommendation.

Our adjusted cost of repair is SGD 14,200.00 to carry out the repairs. Kindly refer to parts and labour portion for a detailed account of the cost estimates.

REMARKS

However, for your information, under normal circumstances, the repair normally would take approximately _10 (Ten) working days to complete.

We have **NOT AUTHORISED** the repair to the damaged vehicle. The survey was conducted strictly on a "WITHOUT PREJUDICE" basis.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our final report, which includes material damages photographs.

Yours faithfully, ICON Motor Appraiser Pte Ltd

Patrick No

Motor Vehicle Appraiser

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

. IGOIN MOTOR APPRAISER PTE LTD

ist it	ems					1
S/N	Parts description	QTY	Condition	Repairer's Estimate	Our Recommendation	
1	Rear windscreen moulding	1	Necessary	\$ 115.90	\$ 115.90	
2	Tailgate	1	Damaged	\$ 1,473.24	\$ 1,473.24	
3	Tailgate dampers	2	Jammed	\$ 148.00	\$ 148.00	XWY
4	Tailgate lock	1	Jammed	\$ 225.00	\$ 225.00	
5	Tailgate lock catch	1	Bent	\$ 49.00	\$ 49.00	
6	Tailgate "NISSAN" logo	1	Necessary	\$ 94.81	\$ 94.81	
7	Tailgate outer garnish	1	Damaged	\$ 225.70	\$ 225.70	
8	Tailgate weatherstrip		Deformed	\$ 186.00	\$ 186.00	
9	Tailgate side stopper sockets	2	Necessary	\$ 28.00	\$ 28.00	
10	Taillamp C319.70	2.	Damaged	\$ 916.00	\$ 916.00	639
11	Taillamp panel @ 265.50 cach	2	Buckled	\$ 652.00	\$ 652.00	531
12	Taillamp inner panel	2.2	Distorted	\$ 1,378.00	\$ 1,378.00	RY
13	End panel	1	Buckled	\$ 354.00	\$ 354.00	
14	End panel inner	1	Buckled	\$ 548.00	\$ 548.00	247.
15	End panel top garnish	1	Cracked	\$ 124.00	\$ 124.00	
16	Rear bumper	71	Damaged	\$ 788.00	\$ 788.00	485
17	Rear bumper tow cover	1	Damaged	\$ 49.50	\$ 49.50	
18	Rear bumper side retainer	2	Cracked	\$ 242.00	\$ 242.00	
19	Rear exhaust mounting	2	Necessary	\$ 96.00		Xnn
20	Rear exhaust assy	1,12	Bent	\$ 945.00	\$ 945.00	RX
21	Rear bumper sponge	1	Damaged	\$ 121.00	\$ 121.00	
22	Tailgate "NV200" emblem		Necessary	\$ 56.40	\$.56.40	1
23	Tailgate "VANETTE" emblem	1	Necessary	\$ 42.90	\$ 42.90	1
24	Rear fender	2	Distorted	\$ 1,892.60		┥
25	Rear fender inner panel	2	Distorted	\$ 1,274.80	\$ 1,274.80	⊣ ′′
26	Floor panel	1	Buckled	\$ 1,295.00		41.7/
27	Floor panel top mat	1	Deformed	\$ 653.40		- I " " " " " " " " " " " " " " " " " "
. 28	Rear chassis extension member	1	Bent	\$ 854.00		-1''
29	Spare tyre bracket	1	Bent	\$ 361.00		198
30	Spare tyre bracket lock	1	Bent	\$ 59.80	\$ 59.80	
31	Rear side air vent	2	Re-use			
	•		Subtota			
Discount (less 10.00%					\$ 1,524.91	
		Tota	\$ 15,249.05	\$ 13,724.15	: 1	

7793.35

No.	Parts description	QTY	Condition	partition and the	
1	Rear windscreen sealant	- 411		Repairer's Estimate	Our Recommendation
2	Tailgate "6 Pax" sticker	1	Necessary	\$ 100.00	\$ 80.00
		1.1	Necessary	\$ 25.00	\$ 25.00
3	Tailgate "70km/h" sticker	1	Necessary	\$ 25.00	\$ 25.00
4	Reverse sensor	1	Damaged	\$ 280.00	\$ 250.00
5	End panel sealant	1	Necessary	\$ 80.00	\$ 60.00
6	End panel top garnish clips	6	Necessary	\$ 40.00	\$ 30.00
7	Rear bumper clips	12	Necessary	\$ 60.00	\$ 50.00
8	Floor panel sealant	1	Necessary	\$ 100.00	\$ 80.00
9	Sundries	1	Necessary	\$ 60.00	\$ 50.00
			Total	\$ 770.00	\$ 650.00

Labo	ur						7
No.	Description	QTY Repairer's Estimate		Our Recommendation		1	
1	To dismantle / renew the accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	1	\$	1,800.00	\$	1,600.00	1400
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	1	\$	60.00	\$	40.00	
3	To remove, refit tailgate components to replace tailgate, check and re-adjust close gap, alignment and water seepage.	1	\$	120.00	\$	100.00	60
4	To remove and replace exhaust silencer.	1	\$	150.00	\$	120.00	80
5	To remove and refit rear windscreen to facilitate repair work.	1	\$	150.00	\$.	120.00	~
6	Supply spray paint material and necessary items to respray affected area / panel.	1	\$	1,600.00	\$	1,400.00	1200
7	To rust proof all affected portions after repair.	1	\$	100.00	\$	80.00	50
		otal labour	\$	3,980.00	\$	3,460.00	1

Estimate Grand Total \$ 19,999.05 \$ 17,834.15

7014.01 430 2950 10394.01 US\$8300 (Ways