



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Ref: CS/FCI22008051/Kvy3m4

Date: 07/09/2022

Code: FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 7616Y	Veh. Inspected	GBC 7349J
Policy No.	D-22098725MFVS/6	Coverage (\$)	0.00
Claim No.	D22002089MFVS	Excess (\$)	0.00
Assign From	JOANNE TAN JO ANN	Assign Date	22/08/2022

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE (A)	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	JTFPT22P600011782	Colour	WHITE
Odometer	357614 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15X8	BRIDGESTONE	7 mm
L/H Front Tyre	195 R15X8	BRIDGESTONE	7 mm
R/H Rear Tyre	195 R15X8	BRIDGESTONE	2 mm
L/H Rear Tyre	195 R15X8	BRIDGESTONE	2 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	01/07/2022	Inspection Date	23/08/2022
Survey held at	BLK 160 SIN MING DRIVE #02- 01 AUTOCITY		
Repairer	MEGA AUTO PTE LTD		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **2 Working Days**