

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/GRB22008053/UPA3Q2**Date:** 06/07/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01
Claimant Vehicle No : SMD2610B **Insured Vehicle No :** SMM7769Y
 Date of Loss: 20/08/2022 Nature of Claim: TP Claim No: MFL2022D0004549

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMD2610B**
 Make & Model: MERCEDES-BENZ CLA180, 1.6 AMG LINE (R18 BI) (A) Engine No: 27091031591947
 Reg. Date: 10/08/2018 (Man. Year: 2018) Chassis No: WDD1173422N644147
 Colour: Red Odometer: 68510 km
 Engine Capacity: 1595 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40Z R18 Rear Tyre Size: 225/40Z R18
 Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm
 Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,270.50	5,581.80	8,688.70	60.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,750.00	1,590.00	2,160.00	57.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,020.50	7,171.80	10,848.70	60.20
Approved Total (Overridden) (S\$)		5,700.00		
Nett Amount (S\$)	18,020.50	5,700.00	12,320.50	68.37
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,007.45		
Global Sum Settlement (S\$)		6,000.00		

INSPECTION

Date of Assignment: 23/08/2022
 Date Inspected: 23/08/2022 Inspected At: Choo Motor Spray Painter (HQ)
 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Oct 2022)
Parts:	143	MERCEDES-BENZ CLA180 1.6 AMG LINE (R18 BI) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMD2610B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	2,245.00 F	*- FL
2	1		*BOOTLID OUTER CHROME MOULDING	Not Necessary	461.50 F	*- FL
3	1		*BOOTLID CLA 180 EMBLEM	Not Necessary	95.00 F	*- FL
4	1		*BOOTLID C&C LOGO	Not Necessary	50.00 F	*- FL
5	2		*BOOTLID HINGES	Not Necessary	730.00 F	*- FL
6	1		*BOOTLID WEATHERSTRIP	Twisted	368.00 F	*266.00 FL
7	1		*BOOTLID INNER LOCK	Not Necessary	455.00 F	*- FL
8	1		*BOOTLID INNER TRIM LOWER GARNISH	Not Necessary	365.00 F	*- FL
9	1		*BOOTLID INNER TRIM LOWER	Not Necessary	485.00 F	*- FL
10	1		*SET BOOTLID INNER TRIM CLIPS	Not Necessary	60.00 F	*- FL
11	1		*TAILLAMP	N/S Cracked	1,900.00 F	*805.00 FL
12	2		*TAILLAMP BLACK GARNISHS	Not Necessary	136.00 F	*- FL
13	1		*TAILLAMP LOWER BRACKETS	N/S Cracked	210.00 F	*105.00 FL
14	1		*REAR BUMPER	Dented / Deformed	1,615.00 F	*1,615.00 FL
15	1		*REAR BUMPER LOWER SPORT	Distorted	1,580.00 F	*1,200.00 FL
16	1		*REAR BUMPER EXHAUST CHROME N/S	Serviceable	230.00 F	*- FL
17	1		*SET REAR BUMPER CLIPS	Necessary	60.00 F	*60.00 FL
18	1		*REAR BUMPER INNER TOP RETAINER	Not Necessary	345.00 F	*- FL
19	1		*REAR BUMPER BEAM	Bent	750.00 F	*681.00 FL
20	1		*REAR END PANEL	Dented	1,215.00 F	*1,205.00 FL
21	1		*REAR END PANEL TOP GARNISH	Not Necessary	485.00 F	*- FL
22	1		*REAR END PANEL SEALANT	Necessary	50.00 F	*50.00 FL
23	1		*REAR BUMPER REVERSE SENSOR (N/S)	Shorted	380.00 F	*215.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	14,270.50	6,202.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	620.20
Total Parts (S\$)	14,270.50	5,581.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REAR REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	0.00
4	TO TRANSFER BOOTLID MECHANISM	New	100.00	0.00
5	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	150.00	80.00
6	TO DISMANTLE & REFIX FUEL TANK	New	100.00	0.00
7	TO SPRAY RUST PROOFING	New	120.00	40.00
8	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,500.00	600.00
9	TO PUTTY & SPRAY PAINTING	New	1,500.00	800.00
Gross Labour Cost (\$\$)			3,750.00	1,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >