

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22008055/KPA3Q2**Date:** 30/12/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220060518
Claimant Vehicle No :	SLX4569G	Insured Vehicle No :	SKA1200Y
Date of Loss:	19/08/2022	Nature of Claim:	TP
		Claim No:	3583463307SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLX4569G	Engine No:	2ZR0A70238
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	JTDGG20W00J009222
Reg. Date:	28/03/2018 (Man. Year: 2017)	Odometer:	132229 km
Colour:	Metallic Pearl White		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	957.50	733.75	223.75	23.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,580.00	860.00	720.00	45.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,537.50	1,593.75	943.75	37.19
Approved Total (Overridden) (S\$)		1,250.00		
	(S\$)	2,537.50	1,250.00	1,287.50
+ GST 7.00/7.00% (S\$)		177.63	87.50	90.13
Nett Amount (S\$)	2,715.13	1,337.50	1,377.63	50.74
+ Car Rental (3.0 x S\$100.00/day + 7.00% GST) (S\$)		321.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,660.50		

INSPECTION

Date of Assignment:	23/08/2022	Optima Werkz Pte Ltd (HQ)
Date Inspected:	23/08/2022 Inspected At:	10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK
		Autopoint
		Singapore 568047
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	645.00 FL	*645.00 FL
2	1		*REAR BUMPER SIDE BRACKET RH	Serviceable	95.00 FL	*- FL
3	1		*REAR BUMPER REFLECTOR RH	Serviceable	70.00 FL	*- FL
4	1		*REAR END PANEL (NPA)	Repair	0.00 FL	*- FL
5	1		*REAR TAILGATE (NPA)	Repair	0.00 FL	*- FL
6	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
7	1		*REAR BUMPER REVERSE SENSOR	Shorted	300.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	1,160.00	895.00
- List Item Discount on L Items 25.00/25.00% (S\$)	202.50	161.25
Total Parts (S\$)	957.50	733.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX ,REPAIR & READJUST REAR ACCIDENT AREAS & ETC	New	700.00	400.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER ,REAR TAILGATE ,REAR END PANEL & ETC	New	700.00	400.00
3	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC	New	100.00	50.00
4	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	80.00	10.00
Gross Labour Cost (\$\$)			1,580.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >