

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT LONPAC INSURANCE BHD Ref: CS3/LPC22008063/Sqy3e2 300 BEACH ROAD Date: 30/08/2022 #17-04/07 THE CONCOURSESINGAPORE 199555 Code: LPC2 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **GBD 858Y** XD 2975T Veh. Inspected Policy No. Coverage (\$) 0.00 Claim No. 22/22/22/VC05/026010 Excess (\$) 0.00 **GERALD POH Assign Date** 22/08/2022 Assign From **Vehicle Particulars & Condition** 2. ISUZU CYZ52L Make & Model 15681 C.C HIDDEN 2008 Engine No. Year of Reg. JALCYZ52L87000068 WHITE Chassis No. Colour Odometer 176083 KM Steering **IN ORDER IN ORDER** NIL **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 295/80 R22.5 **ECOSTAR** 8 mm 295/80 R22.5 **ECOSTAR** L/H Front Tyre 8 mm 295/80 R22.5 (D) **KPATOS** R/H Rear Tyre 7/7 mm 295/80 R22.5 (D) 7/7 mm **KPATOS** L/H Rear Tyre 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. 5. **General Information** 06/07/2022 23/08/2022 (03:43 PM) Inspect Date / Time Accident Date K & M LEASING PTE LTD Survey held at 51 UBI AVENUE 1#03-18 PAYA UBI INDUSTRIAL PARK SINGAPORE 408933

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

Report Ref No. CS3/LPC22008063/Sqy3e2

Inspected By

S MOHAMED IRFAN BIN MOHAMED IQUBAL

K.K.LAU CPT(RET)

Asst. Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser