

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22008072/AGCY3M4
Date: 04/04/2023**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001961745
Claimant Vehicle No :	SMM853H	Insured Vehicle No :	SLR6547M
Date of Loss:	21/08/2022	Nature of Claim:	TP
		Claim No:	282669

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM853H	Engine No:	G4FGKU109570
Make & Model:	HYUNDAI AD AVANTE, 1.6 GLS (A)	Chassis No:	KMHD841CMKU879035
Reg. Date:	17/06/2019 (Man. Year: 2019)	Odometer:	0 km
Colour:	Black		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,370.72	6,442.80	6,927.92	51.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,230.00	2,670.00	2,560.00	48.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,600.72	9,112.80	9,487.92	51.01
Approved Total (Overridden) (S\$)		7,300.00		
Nett Amount (S\$)	18,600.72	7,300.00	11,300.72	60.75

INSPECTION

Date of Assignment:	23/08/2022	2020 SPRAY PAINTING PTE LTD 8 KAKI BUKIT AVENUE 4, #03-19, PREMIER @ KAKI BUKIT, SINGAPORE 415875
Date Inspected:	23/08/2022 Inspected At:	
Estimated Period of Repair:	7.0 days	

Adjuster: XING GUO QIANG**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 04 Apr 2023)
Parts: 143	HYUNDAI AD AVANTE 1.6 GLS (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMM853H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	474.90 FL	*474.90 FL
2	1		*REAR BUMPER SIDE HOLDER RH	Not Necessary	35.80 FL	*- FL
3	1		*REAR RH FENDER	Repair	1,854.90 FL	*- FL
4	1		*REAR RH FENDER INNER SHIELD	Not Necessary	165.90 FL	*- FL
5	1		*REAR WINDSCREEN MOULDING	Not Necessary	159.40 FL	*- FL
6	1		*REAR RH DOOR	Dented	1,846.90 FL	*1,846.90 FL
7	1		*REAR RH DOOR LOCK	Not Necessary	247.80 FL	*- FL
8	1		*REAR RH DOOR WEATHERSTRIPE	Not Necessary	135.80 FL	*- FL
9	1		*REAR RH DOOR INNER TRIM BOARD	Cracked	645.60 FL	*645.60 FL
10	1		*REAR RH DOOR GLASS REGULATOR GEAR	Damaged	185.60 FL	*185.60 FL
11	1		*REAR RH DOOR GLASS REGULATOR MOTOR	Not Necessary	365.20 FL	*- FL
12	2		*REAR DOOR HINGE	Not Necessary	95.00 FL	*- FL
13	1		*ROCKER PANEL	Repair	1,545.00 FL	*- FL
14	1		*FRONT RH DOOR	Dented	1,785.60 FL	*1,785.60 FL
15	1		*FRONT RH DOOR LOCK	Not Necessary	268.10 FL	*- FL
16	1		*FRONT RH DOOR WEATHERSTRIPE	Not Necessary	131.70 FL	*- FL
17	1		*FRONT RH DOOR INNER TRIM BOARD	Cracked	664.10 FL	*664.10 FL
18	1		*FRONT RH DOOR REGULATOR GEAR	Damaged	198.10 FL	*198.10 FL
19	1		*FRONT RH DOOR GLASS REGULATOR MOTOR	Not Necessary	378.20 FL	*- FL
20	2		*FRONT DOOR HINGE	Not Necessary	95.00 FL	*- FL
21	1		*FRONT RH FENDER	Dented	1,227.70 FL	*1,227.70 FL
22	1		*FRONT RH FENDER INNER SHIELD	Not Necessary	171.40 FL	*- FL
23	1		*FRONT RH FENDER MUDFLAP	Not Necessary	65.10 FL	*- FL
24	1		*REAR AXLE	Not Necessary	1,388.70 FL	*- FL
25	1		*REAR RH WHEEL HUB C/W BEARING	Not Necessary	456.30 FL	*- FL
26	1		*REAR RH SHOCK ABSORBER	Not Necessary	263.10 FL	*- FL
27	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
28	1		*REAR FENDER INNER SHIELD	Not Necessary	30.00 FS	*- FS
29	1		*REAR FENDER SEALANT	Not Necessary	60.00 FS	*- FS
30	1		*REAR DOOR INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
31	1		*REAR DOOR SURROUND MOULDING	Cut	150.00 FS	*80.00 FS
32	1		*REAR DOOR BLACK TAPE	Necessary	60.00 FS	*60.00 FS
33	1		*ROCKER PANEL SEALANT	Not Necessary	60.00 FS	*- FS
34	1		*FRONT DOOR INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
35	1		*FRONT DOOR SURROUND MOULDING	Cut	150.00 FS	*80.00 FS
36	1		*FRONT DOOR BLACK TAPE	Necessary	60.00 FS	*60.00 FS
37	1		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	30.00 FS	*- FS
38	1		*REAR WHEEL RIM	Cut	800.00 FS	*450.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,340.90	7,848.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,970.18	1,405.70
Total Parts (\$\$)	13,370.72	6,442.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,800.00	1,000.00
2	SPRAY PAINTING	New	1,600.00	1,200.00
3	WIRING	New	100.00	30.00
4	TO APPLY TUFF COAT	New	150.00	60.00
5	TO REMOVE UPHOLSTERY	New	150.00	40.00
6	TO REMOVE REVERSE SENSOR	New	100.00	50.00
7	TO TRANSFER FRONT & REAR DOOR FITTINGS	New	300.00	160.00
8	TO REMOVE FRONT & REAR SEAT	New	250.00	0.00
9	TO DISMANTLE REAR UNDERCARRIAGE	New	380.00	0.00
10	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
11	TO REMOVE REVERSE SENSOR	New	100.00	50.00
12	TO REMOVE REAR EXHAUST PIPE	New	150.00	0.00
			Gross Labour Cost (S\$)	5,230.00
				2,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >