3/15/23, 5:01 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22008073/RQY3E2

15/03/2023 Date:

REFERENCE

No:

Price:

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMCVSNA00155002100

Claimant Vehicle

SJK286R

Insured Vehicle

No:

XE6879G

Date of Loss: 18/08/2022

Nature of Claim: TP

Claim No:

SNM22D205834/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJK286R

VOLKSWAGEN SPORTSVAN, 1.4 (A) Make & Model:

Engine No: CZC524336

30/11/2016 (Man. Year: 2016) Reg. Date:

Chassis No: WVWZZZAUZGW572511 Odometer: 93874 km

Colour: White **Engine Capacity:** 1395 cc

Market Value/New Car

N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Pre-accident Condition: Handbrake (Serviceable): Yes **Engine Modification:** No

CONDITION OF TYRES

225/40 R18 Front Tyre Size: 225/40 R18 Rear Tyre Size: Front Left Side: Rear Left Side: Continental 6 mm Continental 6 mm Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		4,282.06	2,849.01	1,433.05	33.47
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,965.00	1,415.00	550.00	27.99
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	6,247.06	4,264.01	1,983.05	31.74
	Approved Total (Overridden) (S\$)		3,400.00		
	(S\$)	6,247.06	3,400.00	2,847.06	45.57
	+ GST 7.00/7.00% (S\$)	437.29	238.00	199.29	45.57
	Nett Amount (S\$)	6,684.35	3,638.00	3,046.35	45.57

INSPECTION

Date of Assignment: 22/08/2022

AVANTAGE VAG (TOH GUAN) (HQ)

48 Toh Guan Road East, #05-136 Enterprise Hub Date Inspected: 23/08/2022 Inspected At:

Singapore 608586

Estimated Period of Repair: 5.0 days

MOHD RASUL Adjuster: Manager: SHIAU CHAN NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 15 Mar 2023)

Parts: N/A VOLKSWAGEN SPORTSVAN 1.4 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJK286R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH REAR FENDER, OUTER	Bent	1,362.62 FL	*1,362.62 FL
2	1		*RH REAR FENDER, INNER	Repair	810.98 FL	*-FL
3	1		*RH REAR FENDER SHIELD	Torn	135.68 FL	*135.68 FL
4	1		*RH GUIDE PIECE, FENDER	Cracked	32.40 FL	*32.40 FL
5	1		*REAR BUMPER	Torn	945.98 FL	*945.98 FL
6	1		*RH GUIDE PIECE, TAIL-LIGHT	Not Necessary	36.89 FL	*- FL
7	1		*RH PARKING SENSOR, OUTER	Not Necessary	140.40 FL	*- FL
8	1		*RH REAR WHEEL/RIM	Cut	837.61 FS	*600.00 FS
9	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
10	1		*RH REAR TYRE	Not Necessary	276.00 FS	*-FS
F=Fra	anchise	part. S=SpcNe	tt. L=ListItemDisc.			
				Sub Total (S\$)	4,628.56	3,096.68
			- List Item Discoun	t on L Items 10.00/10.00% (S\$)	346.50	247.67
				Total Parts (S\$)	4,282.06	2,849.01

Report was unsubmitted during this print-out.

Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	<u>our Items</u>			
1	TUFF KOTE	New	50.00	30.00
2	REMOVE AND REFIT/CUT AND WELD RH REAR FENDER OUT, INNER, SHIELD, GUIDE PIECES, SENSOR, REAR BUMPER AND OTHER ASSOCIATE COMPONENTS	New	960.00	750.00
3	SURFACE PREPARATION, SPRAY PAINT AND POLISH RH REAR FENDER OUTER, INNER, SENSOR, REAR BUMPER AND OTHER AFFECTED AREAS	. New	750.00	500.00
4	REMOVE, REFIT AND BALANCE RH REAR WHEEL/RIM	New	25.00	25.00
5	CHECK AND ADJUST WHEEL ALIGNMENT	New	100.00	60.00
6	DIAGNOSTIC CHECK AND ERASE FAULT CODES AFTER THE REPAIR	New	80.00	50.00
	Gross Labou	1,965.00	1,415.00	
	Report was unsubmitted during this pr	rint-out.		

< END OF ESTIMATES >