

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22008075/AGVY3E2**Date:** 15/06/2023REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001961100
Claimant Vehicle No :	SKJ4759K	Insured Vehicle No :	SLN6906G
Date of Loss:	12/07/2022	Nature of Claim:	TP
		Claim No:	278923

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKJ4759K	Engine No:	LF11351131
Make & Model:	MAZDA MX-5, 2.0 6AT	Chassis No:	JM0NC30F2C0203262
Reg. Date:	04/04/2013 (Man. Year: 2012)	Odometer:	96626 km
Colour:	Red		
Engine Capacity:	1999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/45 R17	Rear Tyre Size:	205/45 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,695.60	1,379.44	3,316.16	70.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,210.00	630.00	1,580.00	71.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,905.60	2,009.44	4,896.16	70.90
Approved Total (Overridden) (S\$)		1,600.00		
Nett Amount (S\$)	6,905.60	1,600.00	5,305.60	76.83

INSPECTION

Date of Assignment:	23/08/2022	Unimotor Company (HQ)
Date Inspected:	30/08/2022 Inspected At:	1, Kaki Bukit Avenue 6, Autobay@Kaki Bukit, #01-94
Estimated Period of Repair:	2.0 days	Singapore 417883

Adjuster: XING GUO QIANG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 12 Jun 2023)	
Parts:	N/A	MAZDA MX-5 2.0 6AT (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKJ4759K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT ASSY	Not Necessary	1,288.80 FL	*- FL
2	1		*BOOT LOCK	Not Necessary	131.50 FL	*- FL
3	1		*BOOT WEATHERSTRIP	Not Necessary	119.60 FL	*- FL
4	1		*REAR END PANEL	Not Necessary	458.00 FL	*- FL
5	1		*BUMPER ASSY	Deformed	1,185.00 FL	*1,185.00 FL
6	2		*BUMPER SIDE RETAINER	Necessary	164.80 FL	*164.80 FL
7	2		*BUMPER BRACKET	Not Necessary	86.00 FL	*- FL
8	1		*BUMPER REINFORCEMENT	Repair	615.40 FL	*- FL
9	2		*BUMPER GROMMET	Necessary	12.00 FL	*12.00 FL
10	2		*BUMPER SIDE CLIPS	Necessary	47.80 FL	*20.00 FL
11	10		*BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
12	1		*PANEL LINING	Not Necessary	212.30 FL	*- FL
13	1		*EXHAUST PIPE ASSY	Not Necessary	810.30 FL	*- FL
14	2		*EXHAUST MOUNTING	Not Necessary	70.00 FL	*- FL
15	1		*FENDER AIR GRILLE	Not Necessary	55.50 FL	*- FL
16	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
17	1		*REAR EXHAUST CHROME PIPE	Not Necessary	120.00 FS	*- FS
18	1		*REAR REVERSE SENSOR	Damaged	280.00 FS	*250.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,757.00	1,661.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,061.40	282.36
Total Parts (\$\$)	4,695.60	1,379.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISM / RENEW REAR REVERSE SENSOR	New	100.00	50.00
2	TO DISM / REWIRE DAMAGED PORTION	New	120.00	30.00
3	TO SPRAY UNDERCOATING IN REPAIR	New	120.00	0.00
4	TO DISM / REFIX REAR ROOF LINING, PILLAR LINING	New	150.00	0.00
5	TO PANEL BEAT DAMAGED PORTION, CHASSIS FRAME AND RENEW PARTS	New	800.00	300.00
6	TO PUTTY AND RESPRAY DAMAGED PORTION	New	800.00	250.00
7	TO DISM / RENEW EXHAUST BOX	New	120.00	0.00
Gross Labour Cost (S\$)			2,210.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >