

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22008079/TVY3Q2**Date:** 07/06/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00055492201

Claimant Vehicle No : SLU1769G **Insured Vehicle No :** SLA4085G

Date of Loss: 19/08/2022 Nature of Claim: TP Claim No: SNM22D205851/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLU1769G**

Make & Model: BMW 320I, 2.0 ABS D/AB 2WD 2DR GAS/D (A) Engine No: HIDDEN

Reg. Date: 01/02/2009 (Man. Year: 2009) Chassis No: WBAPG56090NL21520

Colour: Black Odometer: 249714 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,925.75	4,559.93	13,365.82	74.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,340.00	1,550.00	2,790.00	64.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,265.75	6,109.93	16,155.82	72.56
Approved Total (Overridden) (S\$)		4,850.00		
(S\$)	22,265.75	4,850.00	17,415.75	78.22
+ GST 8.00/8.00% (S\$)	1,781.26	388.00	1,393.26	78.22
Nett Amount (S\$)	24,047.01	5,238.00	18,809.01	78.22

INSPECTION

Date of Assignment: 23/08/2022

Date Inspected: 23/08/2022 Inspected At: SPEEDWERKZ PTE LTD (HQ)
13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre
Singapore 147807

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Jun 2023)
Parts:	M1-COUPE	BMW 320I 2.0 ABS D/AB 2WD 2DR GAS/D (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU1769G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,575.00 FL	*1,150.20 FL
2	1		*REAR BUMPER RETAINER LH	Necessary	125.00 FL	*125.00 FL
3	1		*REAR BUMPER RETAINER RH	Necessary	125.00 FL	*125.00 FL
4	1		*REAR BUMPER LOWER GARNISH	Deformed	725.00 FL	*273.90 FL
5	1		*REAR BUMPER BRACKET LH	Cracked	115.00 FL	*115.00 FL
6	1		*REAR BUMPER BRACKET RH	Cracked	115.00 FL	*115.00 FL
7	1		*REAR BUMPER REFLECTOR LH	Not Necessary	225.00 FL	*- FL
8	1		*REAR BUMPER REFLECTOR RH	Not Necessary	225.00 FL	*- FL
9	1		*REAR REINFORCEMENT	Bent	825.00 FL	*566.00 FL
10	1		*REAR REINFORCEMENT CENTRE BRACKET	Cracked	345.00 FL	*163.50 FL
11	1		*REAR REINFORCEMENT BRACKET RH	Not Necessary	345.00 FL	*- FL
12	1		*REAR END PANEL	Repair	1,125.00 FL	*- FL
13	1		*REAR END PANEL GARNISH	Deformed	525.00 FL	*244.50 FL
14	1		*TAILLAMP LH	Not Necessary	925.00 FL	*- FL
15	1		*TAILLAMP RH	Not Necessary	925.00 FL	*- FL
16	1		*BOOTLID INNER LOCK	Bent	675.00 FL	*266.00 FL
17	1		*BOOTLID LOGO	Necessary	180.00 FL	*60.00 FL
18	1		*BOOTLID EMBLEM 320I	Necessary	140.00 FL	*60.00 FL
19	1		*BOOTLID	Bent	2,525.00 FL	*1,225.30 FL
20	1		*BOOTLID HINGES	Not Necessary	120.00 FL	*- FL
21	1		*BOOTLID LAMP LH	Not Necessary	625.00 FL	*- FL
22	1		*BOOTLID LAMP RH	Not Necessary	625.00 FL	*- FL
23	1		*EXHAUST PIPE	Not Necessary	3,250.00 FL	*- FL
24	1		*REAR NUMBER PLATE	Bent	90.00 FS	*45.00 FS
25	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
26	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	50.00 FS	*20.00 FS
27	1		*SET REVERSE SENSOR	Not Working	600.00 FS	*200.00 FS
28	1		*REVERSE CAMERA	Not Necessary	500.00 FS	*- FS
29	1		*JOINT SEALANT	Not Necessary	120.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					18,795.00	4,784.40
- List Item Discount on L Items 5.00/5.00% (\$)					869.25	224.47
Total Parts (\$)					17,925.75	4,559.93

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK REAR WIRING AND LIGHTING SYSTEM	New	100.00	30.00
2	REMOVE AND RENEW REAR REVERSE SENSOR	New	120.00	30.00
3	REMOVE AND RENEW REAR REVERSE CAMERA	New	120.00	0.00
4	REMOVE AND REFIT REAR LINING,TRIM AND GARNISH	New	150.00	60.00
5	REMOVE AND RENEW REAR EXHAUST	New	150.00	0.00
6	PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS	New	1,800.00	700.00
7	SPRAY PAINTING ON AFFECTED AREAS	New	1,800.00	700.00
8	APPLY ANTI RUST ON AFFECTED AREAS	New	100.00	30.00
Gross Labour Cost (\$\$)			4,340.00	1,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >