



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 6903A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	O/S SIDE VIEW MIRROR ARM	DAMAGED	1,280.00	1,280.00
1	O/S SIDE VIEW MIRROR COVER	CRACKED	890.00	580.00
1	O/S SIDE VIEW MIRROR GLASS (BIG)	DAMAGED	580.00	580.00
1	O/S SIDE VIEW MIRROR GLASS (SMALL)	BROKEN	467.00	467.00
1	O/S SIDE VIEW MIRROR MOTOR	NOT NECESSARY	786.00	-
1	O/S SIDE VIEW SMALL MIRROR COVER	NOT NECESSARY	468.00	-
1	O/S SIDE VIEW SMALL MIRROR	NOT NECESSARY	318.00	-
1	FRONT PANEL R/H	NOT NECESSARY	1,800.00	-
1	FRONT CAMERA R/H	NOT NECESSARY	589.00	-
1	SIGNAL COVER R/H	NOT NECESSARY	88.90	-
1	FRONT HEADLIGHT R/H	NOT NECESSARY	3,988.50	-
1	FRONT HEADLIGHT L/H	NOT NECESSARY	3,988.50	-
	LESS 10% DISCOUNT		-1,524.39	-
	LESS 15% DISCOUNT		-	-436.05
			13,719.51	2,470.95
	<u>LABOUR</u>			
	TO REMOVE AND REPLACED DAMAGED PARTS.		650.00	280.00
	TO RESPRAY AFFECTED PANEL.		880.00	200.00
	TO CHECK ON ELECTRICAL WIRING FOR CAMERA, HEADLIGHT AND O/S MIRROR.		980.00	50.00
			2,510.00	530.00
	GRAND TOTAL		16,229.51	3,000.95
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,400.00

Report Ref No. CS/SMR22008080/Ucy3m4

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.