



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22008080/Ucy3m4	
			Date: 19/09/2022	
			Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SMB 1627X	Veh. Inspected	PC 6903A
	Policy No.		Coverage (\$)	0.00
	Claim No.	BUS/08/22/7014	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	23/08/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	ISUZU LT434P (M)	c.c	7790
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	JALLT434PG7000077	Colour	MULTI COLOUR
	Odometer	365516 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	295/80 R22.5	PIRELLI	6 mm
	L/H Front Tyre	295/80 R22.5	PIRELLI	6 mm
	R/H Rear Tyre	295/80 R22.5 (D/D)	PIRELLI	6/6 mm
	L/H Rear Tyre	295/80 R22.5 (D/D)	PIRELLI	6/6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	17/08/2022	Inspection Date	23/08/2022
	Survey held at	EURO SUCCESS SERVICES PTE LTD 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	