

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22008081/UQY3Q2**Date:** 13/09/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00220122100

Claimant Vehicle No : SMH626Z **Insured Vehicle No :** SJT732Y

Date of Loss: 20/08/2022 Nature of Claim: TP Claim No: SNM22D205875/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMH626Z**

Make & Model: KIA CERATO, 1.6 (A) Engine No: G4FGJH713013

Reg. Date: 10/01/2019 (Man. Year: 2018) Chassis No: KNAF3416MK5023986

Colour: Red Odometer: 36086 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16

Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8 mm

Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,573.00	1,454.00	1,119.00	43.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,520.00	3,100.00	3,420.00	52.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,093.00	4,554.00	4,539.00	49.92
+ GST 7.00/7.00% (S\$)	636.51	318.78	317.73	49.92
Nett Amount (S\$)	9,729.51	4,872.78	4,856.73	49.92

INSPECTION

Date of Assignment: 23/08/2022

Date Inspected: 24/08/2022 Inspected At: CYCLE & CARRIAGE AUTOMOTIVE PTE LTD (ubi)
330 UBI ROAD 3
Singapore 408650

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Sep 2022)
Parts:	143	KIA CERATO 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMH626Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*UPR COVER -RR BUMPER	Distorted	651.00 FS	*651.00 FS
3	1		*LWR COVER -RR BUMPER	Distorted	241.00 FS	*241.00 FS
4	1		*LH SIDE UPR BRACKET ASSY -RR BPR	Necessary	25.00 FS	*25.00 FS
5	1		*RH SIDE UPR BRACKET ASSY -RR BPR	Necessary	31.00 FS	*31.00 FS
6	1		*LH COVER -RR BUMPER FOG LAMP	Grazed	19.00 FS	*19.00 FS
7	1		*LH LAMP ASSY -SIDE T/SIGNAL	Not Necessary	201.00 FS	*- FS
8	1		*RH COVER -RR BUMPER FOG LAMP	Grazed	19.00 FS	*19.00 FS
9	1		*RH LAMP ASSY -SIDE T/SIGNAL	Not Necessary	201.00 FS	*- FS
10	1		*LH UNDER COVER -RR BUMPER	Not Necessary	33.00 FS	*- FS
11	1		*EXTN WIRING ASSY -BWS	Not Necessary	207.00 FS	*- FS
12	1		*LH UPR BRACKET -RR BEAM MTG	Not Necessary	9.00 FS	*- FS
13	1		*RH UPR BRACKET -RR BEAM MTG	Not Necessary	9.00 FS	*- FS
14	1		*CTR LWR BRACKET -RR BEAM	Not Necessary	6.00 FS	*- FS
15	2		*LWR BRACKET -RR BEAM MTG	Not Necessary	12.00 FS	*- FS
16	1		*ANTENNA ASSY -SMARTKEY	Not Necessary	46.00 FS	*- FS
17	1		*BEAM -RR BUMPER	Cracked	318.00 FS	*318.00 FS
18	1		*LH STAY -RR BUMPER	Bent	65.00 FS	*65.00 FS
19	1		*RH STAY -RR BUMPER	Bent	65.00 FS	*65.00 FS
20	1		*PANEL ASSY -BACK	Repair	324.00 FS	*- FS
21	1		*TRIM ASSY -RR TRANSVERSE	Not Necessary	41.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	2,573.00	1,454.00
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	280.00	280.00
2	TO CHECK WIRING AND ELECTRICAL SYSTEM	New	80.00	80.00
3	TO REMOVE & REINSTALL REAR FLOOR BOARDS ,TRIM AND CARPETS TO FACILITATE REPAIR ON REAR ACCIDENT AFFECTED AREAS	New	640.00	0.00
4	TO REPLACE UPR & LWR REAR BUMPER ,BRACKETS ,CLIPS ,LH & RH T/SIGNAL LAMP & COVER REINFORCEMENT STAY ETC -TO CUT & WELD REAR END PANEL STRAIGHTEN REFORM ALIGN ON REAR ACCIDENT AFFECTED AREAS	New	3,200.00	1,280.00
5	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS (UPPER REAR BUMPER & REAR END PANEL)	New	1,650.00	1,100.00
6	TO CHECK & TEST REVERSE SENSORS	New	100.00	80.00
7	TO SUPPLY ON SET REVERSE SENSOR	New	220.00	220.00
8	TO APPLY SEALANT KIT ON CUT & WELD AREAS	New	200.00	0.00
9	TO APPLY ANTI-CORROSION ON AFFECTED AREAS	New	100.00	60.00
10	TO SUPPLY C&C BADGE	New	50.00	0.00
Gross Labour Cost (\$\$)			6,520.00	3,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >