

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ERGO Insurance Pte. Ltd.
8 Temasek Boulevard, #04-01 Suntec Tower Three
Singapore 038988

Our File No: CS4/EGI22008086/GCY3E2**Date:** 05/12/2022**REFERENCE**

Insured/Claimant:	MAH CHIN FATT	Policy No:	DMPG22000272	
Date of Loss:	18/08/2022	Nature of Claim:	OD	Claim No: CDMPG22001706

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKX9984U		
Make & Model:	HONDA VEZEL, 1.5 X (A)	Engine No:	L15B4025776
Reg. Date:	05/01/2016 (Man. Year: 2015)	Chassis No:	RU11105775
Colour:	White	Odometer:	0 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	S\$51,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	60,159.10	34,724.52	25,434.58	42.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,100.00	4,000.00	1,100.00	21.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	65,259.10	38,724.52	26,534.58	40.66
+ GST 7.00/7.00% (S\$)	4,568.14	2,710.72	1,857.42	40.66
Nett Amount (S\$)	69,827.24	41,435.24	28,392.00	40.66

INSPECTION

Date of Assignment: 23/08/2022

Date Inspected: 24/08/2022 Inspected At:

William's Auto Pte Ltd (HQ)
BLK 3 WOODLANDS ROAD 391-B YEW TEE
INDUSTRIAL ESTATE
Singapore 677965

Estimated Period of Repair: 20.0 days

Adjuster: XING GUO QIANG**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$14,727.76 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Nov 2022)
Parts:	M1-SUV	HONDA VEZEL 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKX9984U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT WINDSCREEN GLASS	Burnt	1,950.60 F	*1,950.60 FL
2	1	*FRONT WINDSCREEN GLASS MOULDING	Burnt	198.20 F	*198.20 FL
3	1	*FRONT WINDSCREEN GLASS RAIN SENSOR	* Check	320.10 F	*- FL
4	1	*FRONT WINDSCREEN GLASS REAR SEE MIRROR	Burnt	196.30 F	*196.30 FL
5	1	*FRONT PILLAR - INNER GARNISH LH	Burnt	189.20 F	*189.20 FL
6	1	*FRONT PILLAR - INNER GARNISH - RH	Burnt	189.20 F	*189.20 FL
7	1	*FRONT DASHBOARD PANEL FACILA	Burnt	1,087.10 F	*1,087.10 FL
8	1	*DASHBOARD / INSTRUMENT PANEL INNER SUPPORT	* Check	557.90 F	*- FL
9	1	*FRONT DASHBOARD PANEL SIDE COVER GARNISH - LH	Burnt	298.40 F	*298.40 FL
10	1	*GLOVE BOX	Burnt	289.60 F	*289.60 FL
11	1	*GLOVE BOX HOUSING	Burnt	175.20 F	*175.20 FL
12	1	*FRONT DASHBOARD PANEL RADIO GARNISH	Burnt	298.20 F	*298.20 FL
13	1	*AIRCON EVOPORATOR COOLING COIL	Burnt	189.30 F	*189.30 FL
14	1	*AIRCON LOUVER GARNISH - H	Burnt	247.20 F	*247.20 FL
15	1	*AIRCON LOUVER GARNISH CENTRE	Burnt	189.20 F	*189.20 FL
16	1	*AIRCON LOUVER GARNISH - RH	Burnt	185.20 F	*185.20 FL
17	1	*INSTRUMENT PANEL INNER SEAL	Burnt	167.20 F	*167.20 FL
18	1	*SPEEDO METER ASSY	Burnt	1,579.20 F	*1,579.20 FL
19	1	*SPEEDO METER SENSOR	Burnt	367.20 F	*367.20 FL
20	1	*SPEEDO METER GARNISH	Burnt	182.50 F	*182.50 FL
21	1	*AUTO GEAR LEVEL COVER	Burnt	134.20 F	*134.20 FL
22	1	*AUTO GEAR LEVER NOB	Burnt	236.30 F	*236.30 FL
23	1	*GEAR LEVEL COVER INNER SUPPORT	Burnt	78.20 F	*78.20 FL
24	1	*AUTO GEAR BOX CONSOLE BOX ASSY	Burnt	1,587.20 F	*1,587.20 FL
25	1	*HAND BRAKE SWITCH	Burnt	156.80 F	*156.80 FL
26	1	*BBC UNIT 06317-T7A-000	* Check	1,980.20 F	*- FL
27	1	*ECU CONTROLLER UNIT	* Check	3,201.30 F	*- FL
28	1	*SET MAIN CABLE	* Check	11,000.00 F	*- FL
29	1	*FUSE BOX	* Check	1,350.20 F	*- FL
30	1	*SET FLOOR MATT COMPLETE	Burnt	1,897.40 F	*1,897.40 FL
31	1	*ROOF TOP PANEL LINING	Burnt	1,289.30 F	*1,289.30 FL
32	4	*ROOF TOP PANEL LINING SIDE HANDLE	Burnt	628.80 F	*628.80 FL
33	1	*ROOF TOP PANEL LINING ROOM LAMP	Burnt	281.40 F	*281.40 FL
34	1	*ROOF TOP PANEL LINING REAR SAFETY BELT	Burnt	220.00 F	*220.00 FL
35	2	*SUN VISOR - LH - RH	Burnt	570.40 F	*570.40 FL
36	2	*FRONT DOOR TRIM BOARD PANEL - LH - RH	Burnt	1,160.00 F	*1,160.00 FL
37	1	*FRONT DOOR TRIM BOARD PANEL MAIN CONTROL SWITCH - RH	Burnt	487.10 F	*487.10 FL
38	1	*FRONT DOOR TRIM BOARD PANEL CONTROL SWICTH - LH	Burnt	246.30 F	*246.30 FL
39	1	*FRONT DOOR TRIM BOARD SPEAKER - RH	Burnt	210.20 F	*210.20 FL
40	1	*FRONT DOOR TRIM BOARD SPEAKER - LH	Burnt	210.20 F	*210.20 FL
41	1	*FRONT DOOR RUBBER - LH	Burnt	329.20 F	*329.20 FL
42	1	*FRONT DOOR RUBBER - RH	Burnt	329.20 F	*329.20 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*FRONT STEP PANEL GARNISH - LH	Burnt	178.20 F	*178.20 FL
44	1		*FRONT STEP PANEL GARNISH - RH	Burnt	178.20 F	*178.20 FL
45	2		*REAR DOOR TRIM BOARD PANEL - LH RH	Burnt	1,040.00 F	*1,040.00 FL
46	1		*REAR DOOR TRIM BOARD CONTROL SWITCH - LH	Burnt	243.10 F	*243.10 FL
47	1		*REAR DOOR TRIM BOARD CONTROL SWITCH - RH	Burnt	243.10 F	*243.10 FL
48	1		*FRONT DASH BOARD AIRBAG ASSY	Burnt	2,803.30 F	*2,803.30 FL
49	1		*FRONT STEERING AIRBAG	Burnt	1,250.40 F	*1,250.40 FL
50	1		*SET AIRBAG STEERING SENSER ASSY	Burnt	720.30 F	*720.30 FL
51	1		*AIRBAG MAIN CONTROL UNIT	Burnt	1,452.10 F	*1,452.10 FL
52	1		*SET AIRBAG FRONTAL SENSER	Burnt	560.00 F	*560.00 FL
53	2		*FRONT SEAT BELT - LH - RH	Burnt	1,420.00 F	*1,420.00 FL
54	1		*STEERING WHEEL	Burnt	2,670.10 F	*2,670.10 FL
55	2		*STEERING WHEEL CONTRO SWITCH - LH - RH	Burnt	394.40 F	*394.40 FL
56	1		*REAR SEAT BELT - LH	Burnt	380.20 F	*380.20 FL
57	1		*REAR SEAT BELT - RH	Burnt	380.20 F	*380.20 FL
58	1		*REAR SEAT BELT COVER GARNISH - LH	Burnt	367.20 F	*367.20 FL
59	1		*REAR SEAT BELT COVER GARNISH - RH	Burnt	367.20 F	*367.20 FL
60	2		*CENTRE PILLAR COVER GARNISH TOP - RH - LH	Burnt	286.40 F	*286.40 FL
61	2		*CENTRE PILLAR COVER GARNISH LOWER - RH - LH	Burnt	312.60 F	*312.60 FL
62	1		*AIRCON BLOWER ASSY	Burnt	1,189.30 F	*1,189.30 FL
63	1		*REAR LUGGAGE CABIN TOP COVER	Burnt	232.10 F	*232.10 FL
64	1		*WIPER PANEL	Burnt	326.20 F	*326.20 FL
65	1		*SET WIPER BLADE	Burnt	98.60 F	*98.60 FL
66	1		*FRONT WINDSCREEN SEALANT	Burnt	80.00 FS	*80.00 FS
67	1		*SET FRONT WINDOW GLASS SOLAR FILM	Burnt	450.00 FS	*450.00 FS
68	1		*SET FRONT & REAR CAR DVR IN UNITCAMERA	Burnt	550.00 FS	*550.00 FS
69	1		*IU BRACKET	Burnt	15.00 FS	*15.00 FS
70	1		*IU UNIT	Burnt	200.00 FS	*200.00 FS
71	1		*RADIO, REVERSE CAMERA AND CD PLAYER	Burnt	730.00 FS	*730.00 FS
72	1		*SET SEATS / CUSHION SPONGE COMPLETE (FRONT & REAR)	Burnt	4,500.00 FS	*4,500.00 FS
73	1		*SET FLOOR RUBBER MAT	Burnt	100.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	60,159.10	41,749.40
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	7,024.88
Total Parts (\$)	60,159.10	34,724.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE DAMAGED AIRBAG, SENSERS, SEAT BELTS, CHECK & CHANGE NEW PARTS, CONDUCT DIAGNOSIS TEST AND RESET	New	800.00	600.00
2	LABOUR TO REMOVE UPHOLSTERY SEATS, TRIM BOARD, INNER COVER GARNISH, FLOOR MAT ENABLE NECESSARY REPAIR AND CLEANING WORKS	New	800.00	500.00
3	WIRING JIB - TO CHECK COMPLETE ELECTRICAL SYSTEM, REWIRING FOR PROPER FUNCTIONING	New	1,800.00	1,600.00
4	LABOUR TO AIRCON JOB, CHECK, DAMAGED AIRCON EVAPORATOR, BLOWER, SWICTH AND CHANGE NEW PARTS AND REFILL GAS	New	700.00	400.00
5	TO SPRAY PAINT ON REPLACEMENT PARTS AND FIRE AFFECTED AREAS	New	1,000.00	900.00
Gross Labour Cost (\$\$)			5,100.00	4,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >