



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 564B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRT BUMPER	DEFORMED	1,151.00	1,151.00
1	FRT BUMPER RETAINER	NOT NECESSARY	24.00	-
1	FRT BUMPER SPONGE	NOT NECESSARY	77.00	-
1	FRT BUMPER REINFORCEMENT	NOT NECESSARY	579.00	-
10	FRT BUMPER CLIPS @\$5.80	NECESSARY	58.00	58.00
1	FRT HEADLAMP RH	NOT NECESSARY	963.00	-
	LESS 20% DISCOUNT		-570.40	-241.80
			2,281.60	967.20
<u>LABOUR</u>				
	TO KNOCK FRT FENDER RH,WELD, REMOVE & FIX ON ABOVE PARTS.		450.00	200.00
	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS.		450.00	200.00
	TO CHECK WIRING.	NOT NECESSARY	30.00	-
	TO DIAGNOSE & RESET FAULT CODE.	NOT NECESSARY	200.00	-
	TO APPLY ANTI RUST COATING.	NOT NECESSARY	60.00	-
			1,190.00	400.00
GRAND TOTAL			3,471.60	1,367.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,050.00

Report Ref No. CS/SPF22008090/Rwy3m4

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$1,050-\$1,500

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.