

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	MS FIRST CAPITA	L INSURANCE LTD		Ref:	CS3/FCI22008091/Gvy3m4
	36 ROBINSON RO #16-01 CITY HOUS		Date:	26/08/2022	
				Code:	FCI2
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SBS 3430Z	Veh. Inspected	t	GBA 7069C
	Policy No.	D-22099187MFBP	Coverage (\$)		0.00
	Claim No.	D22002366MFBP	Excess (\$)		0.00
	Assign From	AINI BINTE	Assign Date		23/08/2022
2. Vehicle Particulars & Condition					
	Make & Model	MERCEDES BENZ VITO 111	c.c		2148
	Engine No.	HIDDEN	Year of Reg.		2007
	Chassis No.	WDF63960323312643	Colour		SILVER
	Odometer	431292 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	205/65 R16	HABILEAD		6 mm
	L/H Front Tyre	205/65 R16	HABILEAD		6 mm
	R/H Rear Tyre	205/65 R16	HABILEAD		6 mm
	L/H Rear Tyre	205/65 R16	HABILEAD		6 mm
4. Description of Damages					
	THE VEHICLE SUS	ISTAINED DAMAGES AT THE REAR PORTION.			
5.	. General Information				
	Accident Date	01/08/2022	Inspect Date /	Time	24/08/2022 (11:00 AM)
	Survey held at	EM SOLUTION PTE LTD			
		160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)MARKET VALUE:\$38,000.00				

Report Ref No. CS3/FCI22008091/Gvy3m4

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor