



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBK 6379L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT WINDSCREEN RUBBER	SERVICEABLE	348.20	-
1	L/H DOOR	BENT	1,208.30	1,208.30
1	L/H DOOR LOCK	JAMMED	262.90	262.90
1	L/H DOOR BOARD	SERVICEABLE	450.33	-
1	L/H DOOR OUTER MOULDING	DENTED	115.30	115.30
1	L/H DOOR RUBBER	SERVICEABLE	195.90	-
1	L/H DOOR REGULATOR	SERVICEABLE	295.65	-
1	L/H POWER WINDOW MOTOR	SERVICEABLE	509.35	-
1	L/H DOOR HINGE	TO REPAIR SEE LABOUR	78.25	-
1	L/H DOOR PILLAR	BENT	460.33	460.33
1	FRONT R/H MUDFLAP	SERVICEABLE	80.50	-
	LESS 25% DISCOUNT		-1,001.25	-511.71
			3,003.76	1,535.12
	<u>SPECIAL NETT ITEMS</u>			
1	COMPANY STICKER (R/H DOOR) (SN)	NECESSARY	30.00	25.00
1	RH DOOR SPEAKER (SN)	SERVICEABLE	250.00	-
			280.00	25.00
	<u>LABOUR</u>			
	TO TRANSFER DOOR MECHANISM TO NEW DOOR.		260.00	60.00
	TO CHECK WIRING.		30.00	20.00
	TO PUTTY AND SPRAY PAINT.		900.00	500.00
	LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF L/H DOOR HINGE.		1,500.00	700.00
			2,690.00	1,280.00
	GRAND TOTAL		5,973.76	2,840.12



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			2,250.00
---	--	--	-----------------

Report Ref No. CS/INC22008095/Kvy3e2

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.