



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

Ref: CS/INC22008095/Kvy3e2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 07/09/2022

ATTN: CYNTHIA ANG

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 5138J	Veh. Inspected	GBK 6379L
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1185289-002	Excess (\$)	0.00
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	23/08/2022

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA (M)	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	JTFAT35Y70K215317	Colour	SILVER
Odometer	79656 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/75 R15	KOMENDO	6 mm
L/H Front Tyre	195/75 R15	KOMENDO	6 mm
R/H Rear Tyre	155 R12X8 (D)	MAXMILER	8/8 mm
L/H Rear Tyre	155 R12X8 (D)	MAXMILER	8/8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/08/2022	Inspect Date / Time	23/08/2022 (02:05 PM)
Survey held at	KANG AUTO ENGINEERING PTE LTD 160 SIN MING DRIVE #02-16 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days