



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBG 3232S

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|--|------------------------------|-----------|---------------------------|-------------------|
| REPLACEMENT OF PARTS | | | | |
| 1 | REAR BUMPER | CRACKED | 529.80 | 529.80 |
| 1 | REAR BUMPER LOWER PAD CENTER | CUT | 65.80 | 65.80 |
| 10 | REAR BUMPER CLIPS @\$4.20 | NECESSARY | 42.00 | 42.00 |
| | LESS 20% DISCOUNT | | -127.52 | -127.52 |
| | | | 510.08 | 510.08 |
| SPECIAL NETT ITEMS | | | | |
| 1 | REAR BUMPER SENSOR (SN) | DAMAGED | 280.00 | 200.00 |
| | | | 280.00 | 200.00 |
| LABOUR | | | | |
| | TO REPAIR DAMAGE. | | 380.00 | 300.00 |
| | TO SPRAY PAINTING. | | 380.00 | 350.00 |
| | | | 760.00 | 650.00 |
| GRAND TOTAL | | | 1,550.08 | 1,360.08 |
| RECOMMENDED COST OF REPAIRS (CONFIRMED) | | | | 1,360.08 |

Report Ref No. CS/INC22008097/Gcy3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.