

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	INCOME INSURAN	ICE LTD		Ref:	CS3/INC22008100/Tny3m4
	75 BRAS BASAH FINCOME CENTRE	ROAD SINGAPORE 189557		Date:	19/12/2022
	ATTN: ENG HUEY	HUEY		Code:	INC
1.	Policy Particulars :- (THIRD PARTY CLAIM)				M)
	Insured Veh.	YP 815K	Veh. Inspected		YP 745D
	Policy No.		Coverage (\$)		0.00
	Claim No.	MT/1184846-001	Excess (\$)		0.00
	Assign From	HAZALYSA BINTE IBRAHIM	Assign Date		23/08/2022
2. Vehicle Particulars & Condition					
	Make & Model	HINO XZU710R	c.c		4009
	Engine No.	HIDDEN	Year of Reg.		2015
	Chassis No.	JHHUCT3H30K015430	Colour		WHITE
	Odometer	152870 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		NIL
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	195/85 R16	DUNLOP		6 mm
	L/H Front Tyre	195/85 R16	DUNLOP		6 mm
	R/H Rear Tyre	195/85 R16 (D)	DUNLOP		6/6 mm
	L/H Rear Tyre	195/85 R16 (D)	DUNLOP		6/6 mm
4. Description of Damages					
	THE VEHICLE SUS	STAINED DAMAGES AT THE FRONT PORTION.			
5.	General Information				
	Accident Date	17/08/2022	Inspect Date / 1	Гime	23/08/2022 (01:00 PM)
	Survey held at	TAN ENG HUAT MOTOR			
		BLK 6 DEFU LANE 10 #01-556 . SINGAPORE 539187			
5a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/INC22008100/Tny3m4

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser