

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22008105/TVY3Q2**Date:** 05/04/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00130132200		
Claimant Vehicle No :	GBL4450X	Insured Vehicle No :	SKJ2406S		
Date of Loss:	19/08/2022	Nature of Claim:	TP	Claim No:	SNM22D205876/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBL4450X	Engine No:	HR16190287D
Make & Model:	NISSAN NV200, 1.6 MT PETROL (A)	Chassis No:	JN1YAAM20Z0002351
Reg. Date:	02/08/2021 (Man. Year: 2021)	Odometer:	38962 km
Colour:	Black		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	165/80 R14	Rear Tyre Size:	165/80 R14
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,225.50	6,366.50	5,859.00	47.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,250.00	2,210.00	3,040.00	57.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,475.50	8,576.50	8,899.00	50.92
Approved Total (Overridden) (S\$)		6,500.00		
Nett Amount (S\$)	17,475.50	6,500.00	10,975.50	62.81

INSPECTION

Date of Assignment:	24/08/2022		
Date Inspected:	24/08/2022	Inspected At:	BLK 1 KAKI BUKIT AVENUE 6 #01-08 AUTOBAY @ KAKI BUKIT SINGAPORE 417883 Repairer: Tsl Auto Garage (HQ)
Estimated Period of Repair:	7.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 04 Apr 2023)	
Parts:	N/A	NISSAN NV200 1.6 MT PETROL (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBL4450X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	520.00 FL	*520.00 FL
2	2		*REAR BUMPER SIDE RETAINER	Deformed	220.00 FL	*220.00 FL
3	1		*REAR BUMPER SPONGE	Cracked	210.00 FL	*210.00 FL
4	1		*REAR BUMPER TOWING CAP	Deformed	95.00 FL	*50.00 FL
5	1		*REAR TAILGATE	Bent	1,920.00 FL	*1,795.00 FL
6	1		*REAR TAILGATE NUMBER PLATE GARNISH	Not Necessary	320.00 FL	*- FL
7	1		*REAR TAILGATE LOCK	Bent	420.00 FL	*420.00 FL
8	1		*REAR TAILGATE INNER TRIM	Torn	320.00 FL	*242.00 FL
9	1		*REAR TAILGATE EMBLEM NISSAN	Necessary	195.00 FL	*195.00 FL
10	1		*REAR TAILGATE EMBLEM NV200	Necessary	135.00 FL	*60.00 FL
11	2		*REAR TAILGATE DAMPER	Not Necessary	440.00 FL	*- FL
12	2		*REAR TAILGATE HINGE	Not Necessary	220.00 FL	*- FL
13	1		*REAR TAILGATE OUTER HANDLE	Cracked	330.00 FL	*330.00 FL
14	1		*REAR WIPER MOTOR	Not Necessary	420.00 FL	*- FL
15	2		*REAR TAIL LAMP	Cracked	660.00 FL	*660.00 FL
16	1		*REAR END PANEL -INNER }	Bent	620.00 FL	*640.00 FL
17	1		*REAR END PANEL -OUTER }	Bent	490.00 FL	*- FL
18	1		*REAR END PANEL TOP GARNISH	Deformed	195.00 FL	*195.00 FL
19	1		*REAR SPARE TYRE CARRIER	Bent	320.00 FL	*320.00 FL
20	1		*REAR SPARE TYRE CARRIER LOCK	Not Necessary	110.00 FL	*- FL
21	1		*REAR FLOOR PANEL	Bent	2,061.00 FS	*200.00 FS
22	2		*REAR FENDER INNER TRIM	Not Necessary	660.00 FL	*- FL
23	1		*WEATHERSHIP	Deformed	185.00 FL	*118.00 FL
24	1		*REAR WINDSCREEN MOULDING	Necessary	110.00 FL	*110.00 FL
25	1		*REAR EXHAUST ASSY	Not Necessary	790.00 FL	*- FL
26	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
27	1		*SET REAR BUMPER REVERSE SENSOR	Not Working	250.00 FS	*200.00 FS
28	1		*REAR BUMPER TOP PROTECTOR -BLACK	Deformed	200.00 FS	*50.00 FS
29	1		*SET REAR TAILGATE INNER TRIM CLIPS	Necessary	50.00 FS	*20.00 FS
30	1		*SET REAR END PANEL TOP CLIPS	Necessary	50.00 FS	*10.00 FS
31	1		*SEALANT	Necessary	50.00 FS	*40.00 FS
32	1		*STICKER 70KM/H	Necessary	50.00 FS	*20.00 FS
33	1		*STICKER 6 PAX	Necessary	50.00 FS	*20.00 FS
34	1		*COMPANT STICKER	Necessary	500.00 FS	*300.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,216.00	6,975.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	990.50	608.50
Total Parts (\$\$)	12,225.50	6,366.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO STRAIGHTEN AND PANEL BEAT REAR FRAME MEMBERS ,TO CUT /WELD AND REMOVE AND REFIT ABOVE PARTS	New	2,000.00	1,000.00
2	TO PUTTY ,RE-SPRAY PAINTING AND POLISH REAR AFFECTED AREAS	New	2,000.00	900.00
3	TO RUST PROOF AFFECTED AREAS	New	100.00	30.00
4	TO CHECK AND RECTIFY WIRING	New	100.00	30.00
5	TO REMOVE AND REFIT BUMPER SENSOR	New	100.00	30.00
6	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	150.00	120.00
7	TO CONDUCT DIAGNOSTIC SYSTEMS AND TO CLEAR FAULTS CODE	New	200.00	0.00
8	TO REMOVE AND REFIT REAR FLOOR BOARD ASSY IN ORDER TO WORKS	New	300.00	40.00
9	TO REMOVE AND REFIT UPHOLSTERY SEATS AND INNER TRIM BOARDS	New	300.00	60.00
Gross Labour Cost (\$\$)			5,250.00	2,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >