



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MINISTRY OF DEFENCE

HQ TRANSPORT COMMAND

KRANJI CAMP 3

151 CHOA CHU KANG WAYSINGAPORE 688248

Ref: CC2/MIDA22008114/Epq2

Date: 05/05/2023

Code: MIDA

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	MID 59065	Veh. Inspected	PA 668D
Policy No.	OA22019969	Coverage (\$)	0.00
Claim No.	CY22/MID59065/180822/0031	Excess (\$)	0.00
Assign From		Assign Date	24/08/2022

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JTFST22P600022453	Colour	WHITE
Odometer	50271 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15C	DUNLOP	4 mm
L/H Front Tyre	195 R15C	DUNLOP	4 mm
R/H Rear Tyre	195 R15C	DUNLOP	4 mm
L/H Rear Tyre	195 R15C	DUNLOP	4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	18/08/2022	Inspection Date	08/09/2022
Survey held at	UCB ENGINEERING PTE LTD 2C, JALAN PESAWAT, JURONG, SINGAPORE 619359		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PA 668D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	RHS PANEL	TO REPAIR SEE LABOUR	2,050.00	-
1	REAR LAMP - RH	BROKEN	285.00	285.00
1	REAR BUMPER COVER - RH	CRACKED	205.00	170.00
1	REAR BUMPER	BROKEN	680.00	680.00
	LESS 25% DISCOUNT		-	-283.75
			3,220.00	851.25
	<u>LABOUR</u>			
	LABOUR CHARGES FOR DISMANTLE & ASSEMBLE WINDOW GLASS X2.	NOT NECESSARY	400.00	-
	LABOUR CHARGES FOR REMOVE & REPLACE THE ABOVE DAMAGED PART. INCLUSIVE OF THE REPAIR OF RHS PANEL.		1,800.00	800.00
	TO PUTTY & SPRAY PAINTING ONTO AFFECTED AREAS.		1,000.00	800.00
	WIRING CHARGES.		30.00	30.00
			3,230.00	1,630.00
GRAND TOTAL			6,450.00	2,481.25
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,000.00


Report Ref No. CC2/MIDA22008114/Epq2

CHEN TSUE YEE

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. PA 668D

RE-INSPECTION

