

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMV 6409X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DISTORTED	1,410.30	899.00
2	REAR BUMPER N/S &N/S RETAINER	NOT NECESSARY	260.20	-
1	REAR BUMPER DIFFUSER	DEFORMED	1,135.40	561.00
1	REAR O/S & N/S BUMPER EXHAUST CHROME GARNISH	NOT NECESSARY	810.00	-
1	REAR O/S & N/S BUMPER REFLECTOR (NPA)	NOT NECESSARY	-	-
1	REAR UNDER COVER	DEFORMED	452.60	452.60
1	REAR ANTENNA	NOT NECESSARY	320.00	-
1	REAR ENFORCEMENT	DENTED	1,086.70	598.00
2	REAR REVERSE SENSOR	DAMAGED	1,276.20	638.10
4	REAR REVERSE SENSOR HOLDER	NECESSARY	220.00	100.00
1	REAR LEG SENSOR	NOT NECESSARY	780.80	-
1	REAR TAIL GATE	DENTED	3,554.80	3,554.80
1	REAR TAIL GATE WEATHERSTRIP	NOT NECESSARY	392.00	-
1	REAR TAIL GATE LEXUS EMBLEM	NECESSARY	160.00	160.00
1	REAR TAIL GATE NX300 EMBLEM	NECESSARY	155.00	155.00
1	REAR TAIL GATE INNER TRIM	NOT NECESSARY	696.00	-
1	REAR TAIL GATE LOCK (UPPER)	NOT NECESSARY	592.00	-
1	REAR TAIL GATE LOCK (LOWER) (NPA)	NOT NECESSARY	-	-
1	REAR O/S TAIL LAMP	NOT NECESSARY	1,633.30	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	1,133.30	-
1	REAR END PANEL INNER TRIM	NOT NECESSARY	498.00	-
1	REAR WINDSCREEN MOULDING	NECESSARY	310.20	160.00
	LESS 10% DISCOUNT		-1,687.68	-727.85
			15,189.12	6,550.65
	SPECIAL NETT ITEMS			
10	REAR BUMPER CLIPS (SN)	NECESSARY	80.00	30.00
2	REAR BUMPER SCREW CLIPS (SN)	NECESSARY	10.00	10.00
8	REAR TAIL GATE INNER TRIM CLIPS (SN)	NOT NECESSARY	40.00	-
6	REAR TAIL GATE END PANEL INNER TRIM CLIPS (SN)	NOT NECESSARY	30.00	-

Report Ref No. CS/INC22008115/Avy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

8,030.65

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	120.00	60.00
			280.00	100.00
	<u>LABOUR</u>			
	TO REMOVE AND REFIT REAR DAMAGE PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		1,000.00	600.00
	TO SPRAY PAINTING.		800.00	600.00
	TO REMOVE & REFIT REAR WINDSCREEN.		150.00	120.00
	TO CHECK FOR FAULT CODE AND RE SET ELECTRICAL SYSTEM.	NOT NECESSARY	180.00	-
	TO CHECK WIRING.		100.00	30.00
	TO RE SEAL ANTI RUST.		80.00	30.00
			2,310.00	1,380.00
	GRAND TOTAL		17,779.12	8,030.65

Report Ref No. CS/INC22008115/Avy3m4

XX.X.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

RECOMMENDED COST OF REPAIRS

(CONFIRMED)

1

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.