



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

Ref: CS/INC22008115/Avy3m4

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

Date: 15/05/2023

ATTN: CYNTHIA ANG

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMY 3569X	Veh. Inspected	SMV 6409X
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1185020-002	Excess (\$)	0.00
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	23/08/2022

2. Vehicle Particulars & Condition

Make & Model	LEXUS NX300	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	JTJBABZ905020723	Colour	BRONZE
Odometer	43653 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/60R18	BRIDGESTONE	6 mm
L/H Front Tyre	225/60R18	BRIDGESTONE	6 mm
R/H Rear Tyre	225/60R18	BRIDGESTONE	6 mm
L/H Rear Tyre	225/60R18	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	19/08/2022	Inspect Date / Time	23/08/2022 (06:16 PM)
Survey held at	RYDER AUTO PTE LTD 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**