

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Ryder

Auto Pte Ltd

2nd Floor, 19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Call: 674418277 Fax: 67468277

Acknowledged by Repairer

Signature: SMV6409X

Date: 19/8/22

ESTIMATE OF REPAIR

Model:

LEXUS NX300

13/10/2020

3P:

SMY3569X (NTUC)

Location : T junction of admiralty road & woodland ind rd E4

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1pc	Rear bumper <i>Distorted</i>	1,410.30	899	
2	10pcs	Rear bumper clips <i>Ne</i>		80.00	30
3	2pcs	Rear bumper screw clips <i>Ne</i>		10.00	
4	2 pcs	Rear bumper n/s & n/s retainer <i>Ne n</i>	260.20	X	
5	1pc	Rear bumper diffuser <i>Deland</i>	1,135.40	561	
6	1pc	Rear o/s & n/s bumper exhaust chrome garnish <i>Ne n</i>	810.00	X	
7	1pc	Rear o/s & n/s bumper reflector <i>Ne n</i>	452.60	X	
8	1pc	Rear under cover <i>Deland</i>	320.00	X	
9	1pc	Rear antenna <i>nn</i>	1086.70	598	
10	1pc	Rear enforcement <i>Distorted</i>	1776.20	638.10	
11	2pcs	Rear reverse sensor <i>2 pieces damaged</i>	220.00	100	
12	4pcs	Rear reverse sensor holder <i>Ne n</i>	780.80	X	
13	1pc	Rear leg sensor <i>Ne n</i>	3554.80	X	
14	1 pc	Rear tail gate <i>Distorted</i>	392.00	X	
15	1 pc	Rear tail gate weatherstrip <i>Ne n</i>	160.00	X	
16	1 pc	Rear tail gate LEXUS emblem <i>3 Ne</i>	155.00	X	
17	1 pc	Rear tail gate NX300 emblem	696.00	X	
18	1 pc	Rear tail gate inner trim <i>Ne n</i>		40.00	X
19	8 pcs	Rear tail gate inner trim clips <i>Ne n</i>	592.00	X	
20	1 pc	Rear tail gate lock (Upper) <i>Ne n</i>		X	
21	1 pc	Rear tail gate lock (Lower) <i>Ne n</i>	1633.30	X	
22	1 pc	Rear o/s tail lamp <i>Ne n</i>	1133.30	X	
23	1 pc	Rear end panel <i>Repairs</i>	498.00	X	
24	1 pc	Rear end panel inner trim <i>Ne n</i>		30.00	X
25	6 pcs	Rear tail gate end panel inner trim clips <i>Ne n</i>	310.20	160	
26	1 pc	Rear windscreen moulding <i>3 Ne</i>		120.00	60
27	1 pc	Rear windscreen sealant			
Sub Total:			16,876.80	280.00	0.00
			10%	0%	10%
After Less %:			15,189.12	280.00	0.00
Labour					
1		To remove and refit rear damage parts	1,000.00	600	
2		To spray painting.	800.00	600	
3		To remove & refit rear windscreen.	150.00	120	
4		To check for fault code and re set electrical system.	180.00	X	
5		To check wiring.	100.00	30	
6		To re seal anti rust.	80.00	30	
Sub Total:			2,310.00		
Total:				17,779.12	

TP INC

Veron

7278.50

6550.65

S.N: 100

Adrian L
P/P 23/08/22

04 Days

1380

total 8030.1

(P/P)

Chan San Choon
Director
DipEng, AAE MIMI, MSAE(Aust)



24 hr accident call
SMV6409X ESTIMATEPg1

