

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

INCOME INSURANCE LTD	DAMAGE ASSESSMENT REPORT							
INCOME CENTRESINGAPORE 189557		INCOME INSURAN	ICE LTD	-	Ref:	CS/INC22008117/Avy3e2		
Insured Veh.   SLQ 9913A   Veh. Inspected   SBR 90X				I	Date:	15/11/2022		
Insured Veh.   SLQ 9913A		ATTN: AZHARI AF	IDI	(	Code:	INC		
Policy No.   Coverage (\$)   0.00	1.	Policy Particulars :- THIRD PARTY CLAIM						
Claim No.   MT/1181548-002   Excess (\$)   0.00     Assign From   HAZALYSA BINTE IBRAHIM   Assign Date   23/08/2022		Insured Veh.	SLQ 9913A	Veh. Inspected		SBR 90X		
Assign From		Policy No.		Coverage (\$)		0.00		
Nake & Model   TOYOTA VELLFIRE   C.C   2493		Claim No.	MT/1181548-002	Excess (\$)		0.00		
Make & Model   TOYOTA VELLFIRE   C.C   2493		Assign From	HAZALYSA BINTE IBRAHIM	Assign Date		23/08/2022		
Engine No.	2.		Vehicle Parti	culars & Condition	n			
Chassis No.   AGH300014648   Colour   WHITE		Make & Model	TOYOTA VELLFIRE	c.c		2493		
Odometer 100378 KM Steering IN ORDER Brakes IN ORDER Modification SPORTS RIM  General GOOD  3. Conditions of Tyres    Size   Make   Balance		Engine No.	HIDDEN	Year of Reg.		2015		
Brakes IN ORDER Modification SPORTS RIM  General GOOD  3. Conditions of Tyres  R/H Front Tyre 265/40 R19 MICHELIN 6 mm  L/H Front Tyre 265/40 R19 MICHELIN 6 mm  R/H Rear Tyre 265/40 R19 MICHELIN 6 mm  L/H Rear Tyre 265/40 R19 MICHELIN 6 mm  L/H Rear Tyre 265/40 R19 MICHELIN 6 mm  4. Description of Damages  THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.  DAMAGES SEE DETAILS.  5. General Information  Accident Date 23/07/2022 Inspect Date / Time 23/08/2022 ( 06:11 PM )  Survey held at AP AUTOMOTIVE SERVICES PTE LTD  9006 TAMPINES INDUSTRIAL PARK A SINGAPORE 528840  5a. Remarks  A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		Chassis No.	AGH300014648	Colour		WHITE		
3. Conditions of Tyres    R/H Front Tyre   265/40 R19   MICHELIN   6 mm		Odometer	100378 KM	Steering		IN ORDER		
3. Conditions of Tyres    Size   Make   Balance		Brakes	IN ORDER	Modification		SPORTS RIM		
R/H Front Tyre 265/40 R19 MICHELIN 6 mm  L/H Front Tyre 265/40 R19 MICHELIN 6 mm  R/H Rear Tyre 265/40 R19 MICHELIN 6 mm  L/H Rear Tyre 265/40 R19 MICHELIN 6 mm  L/H Rear Tyre 265/40 R19 MICHELIN 6 mm  4. Description of Damages  THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.  DAMAGES SEE DETAILS.  5. General Information  Accident Date 23/07/2022 Inspect Date / Time 23/08/2022 ( 06:11 PM )  Survey held at AP AUTOMOTIVE SERVICES PTE LTD  9006 TAMPINES ST 93 #01-202 TAMPINES INDUSTRIAL PARK A SINGAPORE 528840  5a. Remarks  A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		General	GOOD					
R/H Front Tyre 265/40 R19 MICHELIN 6 mm  L/H Front Tyre 265/40 R19 MICHELIN 6 mm  R/H Rear Tyre 265/40 R19 MICHELIN 6 mm  L/H Rear Tyre 265/40 R19 MICHELIN 6 mm  L/H Rear Tyre 265/40 R19 MICHELIN 6 mm  4. Description of Damages  THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.  DAMAGES SEE DETAILS.  5. General Information  Accident Date 23/07/2022 Inspect Date / Time 23/08/2022 ( 06:11 PM )  Survey held at AP AUTOMOTIVE SERVICES PTE LTD  9006 TAMPINES ST 93 #01-202 TAMPINES INDUSTRIAL PARK A SINGAPORE 528840  5a. Remarks  A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.	3.		Conditi	ons of Tyres				
L/H Front Tyre 265/40 R19 MICHELIN 6 mm  R/H Rear Tyre 265/40 R19 MICHELIN 6 mm  L/H Rear Tyre 265/40 R19 MICHELIN 6 mm  4. Description of Damages  THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.  DAMAGES SEE DETAILS.  5. General Information  Accident Date 23/07/2022 Inspect Date / Time 23/08/2022 ( 06:11 PM )  Survey held at AP AUTOMOTIVE SERVICES PTE LTD  9006 TAMPINES ST 93 #01-202     TAMPINES INDUSTRIAL PARK A SINGAPORE 528840  5a. Remarks  A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			Size	Make		Balance		
R/H Rear Tyre 265/40 R19 MICHELIN 6 mm  L/H Rear Tyre 265/40 R19 MICHELIN 6 mm  4. Description of Damages  THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.  DAMAGES SEE DETAILS.  5. General Information  Accident Date 23/07/2022 Inspect Date / Time 23/08/2022 ( 06:11 PM )  Survey held at AP AUTOMOTIVE SERVICES PTE LTD  9006 TAMPINES ST 93 #01-202     TAMPINES INDUSTRIAL PARK A SINGAPORE 528840  5a. Remarks  A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		R/H Front Tyre	265/40 R19	MICHELIN		6 mm		
L/H Rear Tyre 265/40 R19 MICHELIN 6 mm  4. Description of Damages  THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.  DAMAGES SEE DETAILS.  5. General Information  Accident Date 23/07/2022 Inspect Date / Time 23/08/2022 ( 06:11 PM )  Survey held at AP AUTOMOTIVE SERVICES PTE LTD  9006 TAMPINES ST 93 #01-202 TAMPINES INDUSTRIAL PARK A SINGAPORE 528840  5a. Remarks  A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		L/H Front Tyre	265/40 R19	MICHELIN		6 mm		
4. Description of Damages  THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.  DAMAGES SEE DETAILS.  5. General Information  Accident Date 23/07/2022 Inspect Date / Time 23/08/2022 ( 06:11 PM )  Survey held at AP AUTOMOTIVE SERVICES PTE LTD  9006 TAMPINES ST 93 #01-202 TAMPINES INDUSTRIAL PARK A SINGAPORE 528840  5a. Remarks  A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		R/H Rear Tyre	265/40 R19	MICHELIN		6 mm		
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.  DAMAGES SEE DETAILS.   5. General Information  Accident Date 23/07/2022 Inspect Date / Time 23/08/2022 ( 06:11 PM )  Survey held at AP AUTOMOTIVE SERVICES PTE LTD  9006 TAMPINES ST 93 #01-202 TAMPINES INDUSTRIAL PARK A SINGAPORE 528840  5a. Remarks  A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		L/H Rear Tyre	265/40 R19	MICHELIN		6 mm		
5. General Information  Accident Date 23/07/2022 Inspect Date / Time 23/08/2022 ( 06:11 PM )  Survey held at AP AUTOMOTIVE SERVICES PTE LTD  9006 TAMPINES ST 93 #01-202 TAMPINES INDUSTRIAL PARK A SINGAPORE 528840  5a. Remarks  A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.	4.		Description of Damages					
Accident Date 23/07/2022 Inspect Date / Time 23/08/2022 ( 06:11 PM )  Survey held at AP AUTOMOTIVE SERVICES PTE LTD  9006 TAMPINES ST 93 #01-202 TAMPINES INDUSTRIAL PARK A SINGAPORE 528840  5a. Remarks  A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.								
Accident Date 23/07/2022 Inspect Date / Time 23/08/2022 ( 06:11 PM )  Survey held at AP AUTOMOTIVE SERVICES PTE LTD  9006 TAMPINES ST 93 #01-202 TAMPINES INDUSTRIAL PARK A SINGAPORE 528840  5a. Remarks  A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.	5	General Information						
Survey held at AP AUTOMOTIVE SERVICES PTE LTD  9006 TAMPINES ST 93 #01-202 TAMPINES INDUSTRIAL PARK A SINGAPORE 528840  5a. Remarks  A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.	J.	Accident Date		_	ime	23/08/2022 ( 06:11 PM )		
9006 TAMPINES ST 93 #01-202 TAMPINES INDUSTRIAL PARK A SINGAPORE 528840  5a. Remarks  A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				<u> </u>		25/05/2022 ( 00:111 111)		
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		ourvey neid at	TAMPINES INDUSTRIAL PARK A SINGAPORE 528840					
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.	5a.		R	emarks				
5b. Estimate Days of Repair			S)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
2020,000000	5b.							
ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days		ESTIMATED NORI	STIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					