LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22008119/UVY3E2

Date: 20/09/2022

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 1001423842

Claimant Vehicle No: SLP9079M

Date of Loss: 21/08/2022 Nature of Claim: TP Claim No: 282974

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMU1878M

 Make & Model:
 VOLVO XC60, 2.0 T5 (A)
 Engine No:
 B4204T232170513

 Reg. Date:
 09/11/2017 (Man. Year: 2017)
 Chassis No:
 YV1UZ10ACJ1009656

Colour: Blue/Brown/Black Odometer: 72202 km

Engine Capacity: 1969 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R18 Rear Tyre Size: 205/60 R18
Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 7 mm
Front Right Side: Yokohama 7 mm
Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		24,617.42	2,830.90	21,786.52	88.50
Miscellaneous Items		0.00	0.00	0.00	
Labour		5,020.00	850.00	4,170.00	83.07
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	29,637.42	3,680.90	25,956.52	87.58
	Approved Total (Overridden) (S\$)		2,900.00		
	(S\$)	29,637.42	2,900.00	26,737.42	90.22
	+ GST 7.00/7.00% (S\$)	2,074.62	203.00	1,871.62	90.22
	Nett Amount (S\$)	31,712.04	3,103.00	28,609.04	90.22

INSPECTION

Date of Assignment: 25/08/2022

Automobile Integrated Management Pte Ltd (HQ)

Date Inspected: 29/08/2022 Inspected At: 23 Kaki Bukit Ave 4 #04-01, Kaki Bukit (South

Wing)

Singapore 415933

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Sep 2022)

Parts: M1-SUV VOLVO XC60 2.0 T5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMU1878M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (TOP)	Cut / Torn	2,856.90 FL	*2,201.00 FL
2	1		*REAR BUMPER TOWING COVER	Not Necessary	54.20 FL	*- FL
3	1		*REAR BUMPER (LOWER)	Not Necessary	1,645.20 FL	*-FL
4	2		*REAR BUMPER REFLECTOR	Not Necessary	387.40 FL	*- FL
5	4		*REAR BUMPER SENSOR	Not Necessary	903.60 FL	*- FL
6	4		*REAR BUMPER SENSOR HOLDER	Not Necessary	169.20 FL	*- FL
7	1		*REAR BUMPER REVERSE SENSOR WIRE HARNESS	Not Necessary	415.80 FL	*- FL
8	2		*REAR BUMPER EXHAUST CHROME PIPE	Not Necessary	770.00 FL	*- FL
9	2		*REAR BUMPER EXHAUST CHROME PIPE BRACKET	Not Necessary	197.40 FL	*- FL
10	1		*REAR BUMPER REINFORCEMENT	Not Necessary	1,254.90 FL	*- FL
11	2		*REAR BUMPER SIDE RETAINER	Not Necessary	251.20 FL	*- FL
12	1		*REAR BUMPER INNER CENTER GARNISH	Not Necessary	145.80 FL	*- FL
13	1		*REAR BUMPER UPPER CENTER GARNISH	Not Necessary	303.60 FL	*- FL
14	2		*TAIL LAMP	Not Necessary	2,051.60 FL	*- FL
15	2		*TAIL LAMP LOWER BRAKET	Not Necessary	197.40 FL	*- FL
16	1		*TAILGATE	Not Necessary	3,458.90 FL	*- FL
17	1		*TAILGATE OUTER GARNISH	Not Necessary	897.50 FL	*- FL
18	1		*TAILGATE EMBLEM XC60	Not Necessary	132.00 FL	*- FL
19	1		*TAILGATE EMBLEM T5	Not Necessary	125.80 FL	*- FL
20	1		*TAILGATE EMBLEM VOLVL	Not Necessary	145.80 FL	*- FL
21	1		*TAILGATE INNER LOCK	Not Necessary	485.20 FL	*- FL
22	1		*TAILGATE LOCK CATCH	Not Necessary	45.20 FL	*- FL
23	1		*TAILGATE WEATHER STRIP	Not Necessary	245.60 FL	*- FL
24	4		*TAILGATE STOPPER	Not Necessary	123.20 FL	*- FL
25	1		*TAILGATE INNER TRIM (LOWER)	Not Necessary	698.50 FL	*- FL
26	1		*REAR END PANEL	Not Necessary	2,908.40 FL	*- FL
27	1		*REAR END PANEL TOP GARNISH	Not Necessary	482.30 FL	*- FL
28	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	1,977.80 FL	*- FL
29	1		*REAR FENDER	Repair	1,987.60 FL	*-FL
30	1		*RIM O/S	Cut	1,121.22 FS	*800.00 FS
31	1		*REAR NUMBER PLATE WITH COVER	Not Necessary	80.00 FS	*-FS
32	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
33	1		*SET REAR BUMPER INNER CENTER GARNISH CLIP	Not Necessary	50.00 FS	*-FS
34	1		*SET REAR BUMPER UPPER CENTER GARNISH CLIP	Not Necessary	50.00 FS	*-FS
35	2		*SET TAIL LAMP CLIP	Not Necessary	100.00 FS	*-FS
36	2		*SET REAR FENDER INNER COWLING CLIP	Not Necessary	100.00 FS	*-FS
37	1		*TAILGATE WINDSCREEN SEALANT	Not Necessary	80.00 FS	*-FS
38	1		*REAR END PANEL SEALANT	Not Necessary	200.00 FS	*- FS
F=Fra	anchise	part. S=Spc	Nett. L=ListItemDisc.		,	

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) - List Item Discount on L Items 10.00/10.00% (S\$)	27,149.22 2,531.80	3,051.00 220.10	
Total Parts (S\$)	24,617.42	2,830.90	_

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labe	our Items			
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	New	1,800.00	400.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,800.00	400.00
3	TUFF COAT	New	200.00	0.00
4	WIRING AND BULB CHECK ON TAILLAMP	New	120.00	0.00
5	REMOVE AND REFIX CUSHION SEAT / UPHOLSTRY TO FACILIATE REPAIR	New	150.00	0.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	180.00	50.00
7	TRANSFER TAILGATE MECHANISM	New	150.00	0.00
8	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
9	REMOVE AND RESET TAILGATE AUTO SYSTEM	New	350.00	0.00
10	REMOVE AND REFIX TAIL GATE WINDSCREEN	New	150.00	0.00
	Gross Labou	ır Cost (S\$)	5,020.00	850.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >