

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III22008124/KCY3M4**Date:** 16/03/2023**REFERENCE**

Insured/Claimant: COMFORTDELGRO RENT-A-CAR PTE LTD Policy No: D20MFL0000326_02

Date of Loss: 16/07/2022

Nature of Claim: OD

Claim No: MFL2022D0003762

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKW7804A**
 Make & Model: TOYOTA WISH, 1.8 CVT (A) Engine No: 2ZR1667736
 Reg. Date: 16/11/2015 (Man. Year: 2015) Chassis No: JTDGG20W10J003106
 Colour: Metallic Black Odometer: 83621 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: S\$56,000.00
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Davanti 9 mm Rear Left Side: Davanti 9 mm
 Front Right Side: Davanti 9 mm Rear Right Side: Davanti 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,742.75	4,974.75	3,768.00	43.10
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,760.00	1,430.00	1,330.00	48.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,513.75	6,415.75	5,098.00	44.28
Approved Total (Overridden) (\$\$)		5,100.00		
- Excess (\$\$)	0.00	750.00	-750.00	
(\$\$)	11,513.75	4,350.00	7,163.75	62.22
+ GST 7.00/8.00% (\$\$)	805.96	348.00	457.96	56.82
Nett Amount (\$\$)	12,319.71	4,698.00	7,621.71	61.87

INSPECTION

Date of Assignment: 24/08/2022 Present Location: ComfortDelGro Engineering Pte Ltd (Braddell)
 Date Inspected: 24/08/2022 Inspected At: ComfortDelGro Engineering Pte Ltd (Braddell)
 205 Braddell Road
 Singapore 579701
 Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Mar 2023)
Parts:	M1-MPV	TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKW7804A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Cracked	626.70 FL	*626.70 FL
2	1		*FRT BUMPER GRILLE ASSEMBLY	Serviceable	440.30 FL	*- FL
3	1		*FRT RH FOGLAMP GARNISH	Serviceable	90.40 FL	*- FL
4	1		*FRT LH FOGLAMP GARNISH	Serviceable	90.40 FL	*- FL
5	1		*FRT RH FOGLAMP	Serviceable	329.00 FL	*- FL
6	1		*FRT LH FOGLAMP	Serviceable	329.00 FL	*- FL
7	1		*RH HEADLAMP	Mtg Broken	1,344.10 FL	*1,344.10 FL
8	1		*LH HEADLAMP	Serviceable	1,344.10 FL	*- FL
9	1		*FRT BONNET	Repair	1,037.80 FL	*- FL
10	1		*FRT BONNET INSULATOR	Serviceable	436.40 FL	*- FL
11	1		*FRT RH FENDER	Bent	1,049.00 FL	*796.90 FL
12	1		*FRT RH FENDER INNER SHIELD	Cracked	183.10 FL	*183.10 FL
13	1		*FRT RH RETAINER (NPA)	Cracked	-	*75.00 FL
14	1		*FRT WIPER TANK	Dented	73.40 FL	*73.40 FL
15	1		*FRT WIPER TANK MOTOR 1	Cracked	310.60 FL	*310.60 FL
16	1		*FRT RH DOOR WING MIRROR ASSEMBLY	Glass Missing	1,335.50 FL	*1,032.00 FL
17	1		*FRT RH DOOR WING MIRROR	Serviceable	94.10 FL	*- FL
18	1		*FRT RH WHEEL RIM (NPA)	Dented	-	*450.00 FS
19	1		*FRT RH KNUCKLE ARM	Bent	666.10 FL	*561.90 FL
20	1		*FRT RH KNUCKLE BEARING	Necessary	77.00 FL	*77.00 FL
21	1		*FRT RH LOWER ARM	Distorted	805.40 FL	*487.60 FL
22	1		*FRT RH LOWER ARM BALLJOINT	Serviceable	278.70 FL	*- FL
23	1		*FRT RH TIE ROD END (NPA)	Serviceable	-	*- FL
24	1		*FRT RH STABILIZER LINK	Serviceable	251.20 FL	*- FL
25	1		*FRT RH ABSORBER	Bent	464.70 FL	*464.70 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,657.00	6,483.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,914.25	1,508.25
Total Parts (\$\$)	8,742.75	4,974.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	To knock & straighten on accident area, to remove & refit front damage parts	New	1,200.00	500.00
2	To putty & respray on front affected area.	New	1,200.00	650.00
3	To check wiring, focus headlamp.	New	100.00	20.00
4	To remove & refit undercarriage to assist work load.	New	200.00	200.00
<u>Supplementary #1</u>				
<u>Labour Items</u>				
5	TO DO WHEEL ALIGNMENT	New	60.00	60.00
Gross Labour Cost (\$\$)			2,760.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >