

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22008125/RVY3E2**Date:** 06/01/2023REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29138355AT2

Claimant Vehicle No : SLQ349M**Insured Vehicle No :** SFY212C

Date of Loss: 22/08/2022

Nature of Claim: TP Claim No: 642453

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLQ349M**

Make & Model: TOYOTA PRIUS HYBRID, 1.8 CVT (A)

Engine No: 2ZRS054899

Reg. Date: 27/06/2017 (Man. Year: 2017)

Chassis No: JTDKB3FU203560860

Colour: Grey

Odometer: 497662 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,364.73	10,284.27	10,080.46	49.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,650.80	9,971.80	4,679.00	31.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	35,015.53	20,256.07	14,759.46	42.15
+ GST 7.00/7.00% (\$\$)	2,451.09	1,417.92	1,033.17	42.15
Nett Amount (\$\$)	37,466.62	21,673.99	15,792.63	42.15

INSPECTION

Date of Assignment: 24/08/2022

Date Inspected: 24/08/2022

Inspected At: Borneo Motors (S) Pte Ltd (Pandan)
2 Pandan Crescent
Singapore 128462

Estimated Period of Repair: 12.0 days

Adjuster: MOHD RASUL**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Dec 2022)
Parts:	144	TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ349M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
2	1		*COVER, FR BUMPER	Deformed	560.30 FS	*420.22 FS
3	1		*SEAL, HOOD TO FR END	Necessary	55.80 FS	*41.85 FS
4	1		*SUPPORT, FR BUMPER	Not Necessary	86.20 FS	*- FS
5	1		*SUPPORT, FR BUMPER	Not Necessary	86.20 FS	*- FS
6	1		*BRACKET, FR BUMPER	Not Necessary	111.80 FS	*- FS
7	1		*HOOD SUB-ASSY	Bent	1,066.30 FS	*799.72 FS
8	1		*GRILLE SUB-ASSY	Not Necessary	374.40 FS	*- FS
9	1		*UNIT, HEADLAMP	Cracked	2,852.40 FS	*2,139.30 FS
10	1		*UNIT, HEADLAMP	Not Necessary	2,852.40 FS	*- FS
11	1		*REINFORCEMENT	Not Necessary	360.10 FS	*- FS
12	1		*COVER, RR BUMPER	Cracked	478.90 FS	*359.17 FS
13	1		*GUARD, RR BUMPER	Deformed	623.50 FS	*467.62 FS
14	4		*PIECE, RR BUMPER	Necessary	18.00 FS	*13.48 FS
15	1		*FILLER, RR BUMPER	Cracked	133.60 FS	*100.20 FS
16	1		*FILLER, RR BUMPER	Not Necessary	133.60 FS	*- FS
17	1		*RETAINER, RR BUMPER	Not Necessary	127.40 FS	*- FS
18	1		*RETAINER, RR BUMPER	Not Necessary	126.10 FS	*- FS
19	1		*PANEL SUB-ASSY, BODY	Bent	707.10 FS	*530.32 FS
20	1		*COVER, FLOOR UNDER	Not Necessary	189.20 FS	*- FS
21	1		*COVER, RR BODY	Missing	249.10 FS	*186.82 FS
22	1		*COVER, FLOOR UNDER	Not Necessary	261.60 FS	*- FS
23	1		*COVER, DECK TRIM, RR	Not Necessary	136.80 FS	*- FS
24	1		*GLASS SUB-ASSY, BACK	Necessary	1,795.00 FS	*1,346.25 FS
25	1		*DAM, WINDOW GLASS	Necessary	31.30 FS	*23.47 FS
26	1		*GLASS SUB-ASSY, BACK	Necessary	821.20 FS	*615.90 FS
27	2		*DAM, SIDE WINDOW	Necessary	12.80 FS	*9.60 FS
28	1		*PANEL SUB-ASSY, BACK	Bent	1,238.40 FS	*928.80 FS
29	1		*WEATHERSTRIP, BACK	Necessary	402.50 FS	*301.87 FS
30	1		*LOCK ASSY, BACK DOOR	Not Necessary	505.50 FS	*- FS
31	1		*LENS & BODY, RR	Not Necessary	489.00 FS	*- FS
32	1		*LENS & BODY, RR	Not Necessary	479.60 FS	*- FS
33	1		*LENS & BODY, RR	Cracked	544.40 FS	*366.75 FS
34	1		*LENS & BODY, RR	Not Necessary	544.40 FS	*- FS
35	3		*SIKA 182010 SIKA TACK GO! (BLA	Necessary	324.00 FS	*243.00 FS
36	2		*SIKA 207. G+P ADHESIVE PRIMER	Necessary	400.00 FS	*300.00 FS
37	1		*BACK SENSOR SILVER METALLIC 1F	Not Working	173.10 FS	*127.20 FS
38	1		*COVER, RR BUMPER	Cracked	12.52 FS	*12.52 FS
39	1		*GARNISH SUB-ASSY	Cracked	753.52 FS	*753.52 FS
40	1		*EMBLEM SUB-ASSY	Necessary	58.05 FS	*58.05 FS
41	1		*PLATE, LUGGAGE COMPT	Necessary	44.32 FS	*44.32 FS
42	1		*PLATE, LUGGAGE COMPT	Necessary	44.32 FS	*44.32 FS

Report was unsubmitted during this print-out.

1/6/23, 11:32 AM				Adjuster Report		
No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett.						
				Total Parts (S\$)	20,364.73	10,284.27
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING AND REFOCUS HEADLAMP FRT PORTION	New	180.00	162.00
2	SUPPLY REGN PLATE (PO#)FRT	New	80.00	0.00
3	REPL ACC AFF PARTS AND PANEL FRT PORTION	New	2,160.00	1,296.00
4	RESPRAY ACC AFF AREA FRT PORTION	New	1,770.00	1,062.00
5	SUPPLY SEALANT (NETT) 3 PANEL	New	240.00	240.00
6	CONDUCT LEAK TEST REAR PORTION	New	180.00	162.00
7	TRANSFER BOOT LID MECHANISM AND REVERSE CAMERA	New	720.00	486.00
8	REPL REAR WINDSCREEN AND FIX GLASS	New	720.00	648.00
9	SUPPLY PHV STICKER (PO#)	New	20.80	20.80
10	R/I INTERIOR TRIMMING TO FAC REPAIR	New	360.00	324.00
11	REPL ACC AFF PARTS AND PANEL REAR PORTION	New	4,320.00	2,592.00
12	RESPRAY ACC AFF AREA	New	3,540.00	2,655.00
13	RESET ECU UPON COMPLETION OF REPAIR	New	180.00	162.00
14	DRILL HOLE AND INSTALL REVERSE SENSOR	New	180.00	162.00
Gross Labour Cost (S\$)			14,650.80	9,971.80

Report was unsubmitted during this print-out.

< END OF ESTIMATES >