



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 3188Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	DEFORMED	1,560.00	1,467.00
1	FRONT BUMPER LOWER LID (BLACK)	CUT	368.00	368.00
1	FRONT BUMPER RH FOGLAMP GARNISH	NOT NECESSARY	88.00	-
1	FRONT BUMPER RH NOZZLE JET	CRACKED	198.00	198.00
1	FRONT BUMPER RH NOZZLE JET BRACKET	NOT NECESSARY	72.00	-
1	FRONT BUMPER RH NOZZLE JET COVER	NOT NECESSARY	69.00	-
1	FRONT BUMPER RH PARKING SENSOR	DAMAGED	195.00	195.00
1	FRONT BUMPER RH PARKING SENSOR 'O' RING	NECESSARY	18.00	18.00
1	FRONT BUMPER RH PARKING SENSOR HOLDER	NECESSARY	25.00	25.00
2	FRONT BUMPER SIDE RETAINER L/R @\$28.00	O/S DAMAGED	56.00	28.00
1	FRONT RH ABS SENSOR	NOT NECESSARY	375.00	-
1	FRONT RH FENDER	DENTED	975.00	975.00
1	FRONT RH FENDER ARCH GARNISH	CUT	268.00	268.00
1	FRONT RH FENDER INNER BRACKET	BENT	92.50	92.50
1	FRONT RH FENDER INNER SHIELD	TORN	125.00	125.00
1	FRONT RH HEADLAMP	CUT	3,332.00	3,332.00
1	FRONT RH KNUCKLE ARM	DAMAGED	1,375.00	1,027.00
1	FRONT RH KNUCKLE ARM BEARING	DAMAGED	670.00	670.00
1	FRONT RH LOWER ARM	BENT	905.00	656.00
1	FRONT RH SHOCK ABSORBER	NOT NECESSARY	780.00	-
1	FRONT RH SHOCK ABSORBER TOP MOUNTING	NOT NECESSARY	269.00	-
1	FRONT RH SPORT RIM	CUT	970.00	970.00
1	FRONT RH TIE ROD END	NOT NECESSARY	205.00	-
	LESS 10% DISCOUNT		-1,299.05	-1,041.45
			11,691.45	9,373.05
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	60.00	30.00
1	SET FRONT BUMPER RIVET (SN)	NECESSARY	100.00	30.00
1	FRONT RH 235/50R18 TYRE (SN)	NOT NECESSARY	600.00	-
1	SET FRONT RH FENDER ARCH GARNISH CLIPS (SN)	NECESSARY	40.00	30.00

Report Ref No. CS/INC22008127/Avy3m4



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET FRONT RH FENDER INNER SHIELD CLIPS (SN)	NECESSARY	50.00	30.00
			850.00	120.00
	<b>LABOUR</b>			
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTNG HEADLAMP FOCUSING. (TO FR).		80.00	30.00
	TO RESET SYSTEM AFTER REPAIR WORKS.		400.00	100.00
	TO REMOVE, CHANGE FRONT SUSPENSION PARTS, ABSORBER, LOWER ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB, DRIVE SHAFT, ANTI-ROLL BAR, TOP-ARM AND STEERING RACK AND PINION.		380.00	220.00
	TO ROAD TEST DRIVING, CHECK AND RESETTNG WHEEL ALIGNMENTS SYSTEM.		100.00	80.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIEDNT.		1,000.00	600.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.		700.00	500.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		100.00	40.00
			2,760.00	1,570.00
<b>GRAND TOTAL</b>			<b>15,301.45</b>	<b>11,063.05</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>8,800.00</b>

Report Ref No. CS/INC22008127/Avy3m4

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.