

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 4737G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	503.04	503.04
1	REAR BUMPER SIDE RETAINER LH	NECESSARY	112.70	112.70
1	REAR BUMPER LOWER COVER	SCRATCHED	654.96	654.96
1	REAR BUMPER UNDER SIDE LH	DEFORMED	232.00	232.00
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	378.32	-
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	TAIL LAMP LH UPP	SERVICEABLE	557.90	-
1	TAIL LAMP LH LOW	SERVICEABLE	570.00	-
	LESS 25% DISCOUNT		-757.73	-381.18
			2,273.19	1,143.52
	NETT ITEMS			
1	REAR REVERSE SENSOR (N)	NOT NECESSARY	135.70	-
1	BOOTLID COMFORT APP (N)	NECESSARY	40.00	40.00
1	BOOTLID COMFORT / TEL NO STICKER (N)	NECESSARY	60.00	60.00
	LESS 10% DISCOUNT		-23.57	-10.00
			212.13	90.00
	SPECIAL NETT ITEMS			
1	REAR BUMPER ADVERTISEMENT (SN)	NECESSARY	50.00	50.00
			50.00	50.00
	<u>LABOUR</u>			
	PANEL BEATING.		750.00	525.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	REMOVE / REFIX UPHOLSTERY REAR.	NOT NECESSARY	90.00	-
	TUFF KOTE.	NOT NECESSARY	60.00	-
	CHECK LIGHTING.		60.00	30.00
			1,560.00	1,055.00
	GRAND TOTAL		4,095.32	2,338.52

Report Ref No. NS/INC22008135/Rqce2





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,850.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)		

Report Ref No. NS/INC22008135/Rqce2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

Tu

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser