

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22008138/KVY3Q2**Date:** 13/09/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00248452100

Claimant Vehicle No : SLK4238E **Insured Vehicle No :** ET800T

Date of Loss: 22/08/2022 Nature of Claim: TP Claim No: SNM22D205919/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLK4238E**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 3ZZ4893823

Reg. Date: 03/06/2009 (Man. Year: 2009) Chassis No: MR053ZEE106146372

Colour: Metallic Gold Odometer: 178415 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15

Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,296.38	678.00	6,618.38	90.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,460.00	410.00	2,050.00	83.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	9,756.38	1,088.00	8,668.38	88.85

INSPECTION

Date of Assignment: 24/08/2022

Date Inspected: 29/08/2022 Inspected At: Sin Ming Autocare BFG Pte Ltd (HQ)
176, Sin Ming Drive #02-05, Sin Ming Autocare Complex
Singapore 575721

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Sep 2022)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK4238E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Repair	1,407.64 F	*- FL
2	1		*BOOT LID WEATHERSTRIP	Serviceable	268.40 F	*- FL
3	1		*BOOT LOCK	Repair	385.25 F	*- FL
4	1		*BOOT EMBLEM LOGO	Not Necessary	85.60 F	*- FL
5	1		*BOOT EMBLEM COROLLA	Not Necessary	72.50 F	*- FL
6	1		*BOOT EMBLEM ALTIS	Not Necessary	85.60 F	*- FL
7	1		*TAIL LAMP LH (CRACKED)	Not Consistent With Impact	615.84 F	*- FL
8	1		*REAR BODY PANEL	Repair	871.00 F	*- FL
9	1		*REAR FENDER LH	Repair	1,082.80 F	*- FL
10	1		*REAR BUMPER	Cracked	795.60 F	*576.00 FL
11	1		*REAR BUMPER BRACKET LH	Cracked	128.40 F	*85.50 FL
12	1		*REAR BUMPER BRACKET RH	Repair	128.40 F	*- FL
13	1		*REAR BUMPER SIDE RETAINER LH	Distorted	128.40 F	*73.50 FL
14	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	128.40 F	*- FL
15	1		*REAR BUMPER REFLECTOR LH	Serviceable	75.60 F	*- FL
16	1		*REAR BUMPER REFLECTOR RH	Serviceable	75.60 F	*- FL
17	1		*REAR BOOT REFLECTOR LH	Serviceable	192.40 F	*- FL
18	1		*REAR BOOT LID EMBLEM 1.6 VVTI	Not Necessary	85.60 F	*- FL
19	1		*REAR BUMPER SPONGE	Cracked	185.00 F	*169.00 FL
20	1		*REAR CHASSIS BRACKET LH	Repair	198.35 F	*- FL
21	1		*REAR REVERSE SENSOR RH	Serviceable	150.00 FS	*- FS
22	1		*REAR REVERSE SENSOR LH	Serviceable	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,296.38	904.00
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	226.00
Total Parts (\$\$)	7,296.38	678.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGED PARTS ,PANEL BEAT ON	New	1,000.00	200.00
2	TO PUTTY ,APPLY PRIMER & SPRAY PAINT ON EFFECTED PORTION	New	1,200.00	200.00
3	TO APPLY RUST-PROOFING ON REPAIRED ,REPLACED PANEL	New	180.00	0.00
4	TO CHECK WIRING FUNCTIONS	New	80.00	10.00
Gross Labour Cost (\$\$)			2,460.00	410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >