

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22008141/RQY3Q2**Date:** 29/03/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00130332100		
Claimant Vehicle No :	SLM2415M	Insured Vehicle No :	SMN9865J		
Date of Loss:	01/09/2021	Nature of Claim:	TP	Claim No:	SNM21D204939/C02/CHEESC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLM2415M	Engine No:	LEB5919212
Make & Model:	HONDA VEZEL, 1.5 HYBRID X (A)	Chassis No:	RU31219203
Reg. Date:	24/03/2017 (Man. Year: 2016)	Odometer:	234082 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,760.48	1,936.00	4,824.48	71.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,340.00	1,410.00	930.00	39.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,100.48	3,346.00	5,754.48	63.23
Approved Total (Overridden) (S\$)		2,650.00		
(S\$)	9,100.48	2,650.00	6,450.48	70.88
+ GST 8.00/8.00% (S\$)	728.04	212.00	516.04	70.88
Nett Amount (S\$)	9,828.52	2,862.00	6,966.52	70.88

INSPECTION

Date of Assignment:	24/08/2022		60 JALAN LAM HUAT# 04-35/36
Date Inspected:	07/09/2021	Inspected At:	CARROS CENTRE, 737869
			SINGAPORE.
Estimated Period of Repair:	5.0 days		Repairer: Lion City Rentals Pte Ltd (HQ)

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Mar 2023)
Parts:	M1-SUV	HONDA VEZEL 1.5 HYBRID X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLM2415M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,450.00 FL	*1,100.00 FL
2	1		*REAR TAILGATE VEZEL EMBLEM	Necessary	86.80 FL	*55.00 FL
3	1		*REAR TAILGATE HONDA EMBLEM	Necessary	81.30 FL	*56.00 FL
4	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	195.00 FL	*164.00 FL
5	1		*REAR TAILGATE WEATHERSTRIP	Necessary	155.00 FL	*155.00 FL
6	1		*REAR TAILGATE LOCK	Not Necessary	550.00 FL	*- FL
7	1		*REAR TAILGATE LOCK CATCH	Not Necessary	180.00 FL	*- FL
8	1		*REAR END PANEL	Repair	830.00 FL	*- FL
9	1		*REAR END PANEL TOP GARNISH	Not Necessary	155.00 FL	*- FL
10	1		*REAR BUMPER	Scratched	955.00 FL	*765.00 FL
11	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
12	1		*SET END PANEL TOP GARNISH CLIPS	Necessary	80.00 FS	*30.00 FS
13	1		*REVERSE SENSOR	Not Necessary	490.00 FS	*- FS
14	1		*SET BODY SEALANT	Not Necessary	300.00 FS	*- FS
15	1		*WINDSCREEN SEALANT	Necessary	2,100.00 FS	*40.00 FS
					Sub Total (\$\$)	
					7,688.10	2,395.00
					- List Item Discount on L Items 20.00/20.00% (\$\$)	
					927.62	459.00
					Total Parts (\$\$)	
					6,760.48	1,936.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO LABOUR CHARGE FOR REMOVING REAR TAILGATE ,REAR END PANEL ,REAR BUMPER OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS	New	900.00	600.00
2	TO RESPRAY REAR TAILGATE ,END PANEL AND SPARE TYRE PANEL	New	1,000.00	600.00
3	TO REMOVE AND INSTALL REAR TAILGATE GLASS	New	160.00	120.00
4	TO APPLY RUST PROOFING ON ALL DAMAGED PARTS	New	180.00	40.00
5	TO CHECK WIRING SYSTEM	New	100.00	50.00
Gross Labour Cost (\$\$)			2,340.00	1,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >