

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22008144/UNY3Q2**Date:** 05/10/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00045202203	
<b>Claimant Vehicle No :</b>	XD3321Z	<b>Insured Vehicle No :</b>	GBH2701G	
Date of Loss:	12/08/2022	Nature of Claim:	TP	Claim No: SNM22D205647/C02/KHONGLH

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>XD3321Z</b>		Engine No:	50520863582086
Make & Model:	MAN TGS 26.360, 10.5 D 6X4 (M)		Chassis No:	WMA18SZZ79W127836
Reg. Date:	16/12/2008 (Man. Year: 2008)		Odometer:	423999 km
Colour:	Blue			
Engine Capacity:	10518 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>			

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	315/80 R22.5	Rear Tyre Size:	315/80 R22.5 (D/D)
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7/7/7/7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7/7/7/7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,675.90	1,689.31	6,986.59	80.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,680.00	620.00	1,060.00	63.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>10,355.90</b>	<b>2,309.31</b>	<b>8,046.59</b>	<b>77.70</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,800.00</b>		
<b>(\$\$)</b>	10,355.90	1,800.00	8,555.90	82.62
<b>+ GST 7.00/7.00% (\$\$)</b>	724.91	126.00	598.91	82.62
<b>Nett Amount (\$\$)</b>	<b>11,080.81</b>	<b>1,926.00</b>	<b>9,154.81</b>	<b>82.62</b>

**INSPECTION**

Date of Assignment:	24/08/2022	
Date Inspected:	05/09/2022 Inspected At:	Hock Wah Motor Workshop Pte Ltd (Bedok) Blk 3011, Bedok Industrial Park E., #01- 2008/2010/2012 Singapore 489977
Estimated Period of Repair:	2.0 days	

**Adjuster:** MARCUS CHUA**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 03 Oct 2022)	
<b>Parts:</b>	N/A	MAN TGS 26.360 10.5 D 6X4 (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for XD3321Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WHEEL ARCH TOP LH (Deformed)	Not Consistent With The Impact	1,866.50 F	*- FL
2	1		*REAR WHEEL ARCH FRONT LH	Not Necessary	1,866.50 F	*- FL
3	1		*REAR WHEEL ARCH REAR LH	Distorted	1,866.50 F	*1,150.00 FL
4	1		*REAR MUDFLAP LH	Torn	275.60 F	*220.00 FL
5	1		*REAR LAMP LH	Cracked	1,952.40 F	*380.00 FL
6	1		*REAR WHEEL BAR LH	Repair	652.50 F	*- FL
7	1		*REAR REFLECTOR STICK LH	Cracked	115.90 F	*115.90 FL
8	1		*REAR STICKER -60KM/H	Necessary	50.00 FS	*10.00 FS
9	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
					<b>Sub Total (S\$)</b>	<b>8,675.90 1,875.90</b>
					<b>- List Item Discount on L Items 0.00/10.00% (S\$)</b>	<b>0.00 186.59</b>
					<b>Total Parts (S\$)</b>	<b>8,675.90 1,689.31</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	800.00	400.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	800.00	200.00
3	WIRING	New	80.00	20.00
<b>Gross Labour Cost (S\$)</b>			<b>1,680.00</b>	<b>620.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >