



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 6616E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	TO REPAIR SEE LABOUR	695.00	-
1	FRONT BUMPER TOW COVER	SERVICEABLE	25.00	-
1	FRONT RADIATOR GRILLE	CUT	500.00	425.00
1	FRONT RADIATOR GRILLE MOULDING (CHROME)	DENTED	450.00	420.00
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	237.50	-
1	FRONT BUMPER LOWER LIP (SILVER)	SERVICEABLE	187.50	-
1	FRONT BUMPER TOP COVER	SERVICEABLE	95.00	-
1	FRONT LOGO EMBLEM	NECESSARY	86.00	51.00
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	425.00	-
1	FRONT FENDER INNER SHIELD RH	SERVICEABLE	50.00	-
1	FRONT HEADLAMP RH	SERVICEABLE	1,730.00	-
1	FRONT HEADLAMP LOWER BRACKET RH	SERVICEABLE	20.00	-
1	FOG LAMP COVER	SERVICEABLE	93.00	-
	LESS 10% DISCOUNT		-	-89.60
			4,594.00	806.40
<b><u>SPECIAL NETT ITEMS</u></b>				
7	BUMPER CLIP (SN)	NOT NECESSARY	49.00	-
1	LICENSE PLATE WITH CASING (SN)	BENT	45.00	45.00
7	FENDER CLIP (SN)	NOT NECESSARY	49.00	-
			143.00	45.00
<b><u>LABOUR</u></b>				
	TO DISMANTLE & REFIX FRONT ACCIDENT POTION, FRONT BUMPER, FRONT FENDER, FRONT BONNET AND ALL THE EFFECTED AREAS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER & FRONT FENDER RH.		1,200.00	150.00
	TO CHECK WIRING OF ACCIDENT POTION FOR PROPER FUNCTION INCLUDING ADJUST HEADLAMP LH/RH FOCUS.	NOT NECESSARY	120.00	-
	TO APPLY TUFF COASTING.	NOT NECESSARY	150.00	-

Report Ref No. CS/INC22008146/Kqy3m4



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESPRAY FRONT ACCIDENT PORTION, FRONT BUMPER, FRONT BONNET AND ALL THE EFFECTED AREAS.		1,000.00	200.00
			2,470.00	350.00
<b>GRAND TOTAL</b>			<b>7,207.00</b>	<b>1,201.40</b>
<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>				<b>1,201.40</b>

Report Ref No. CS/INC22008146/Kqy3m4

**KONG SENG CHEONG**

Licensed Appraiser

**K.K.LAU CPT(RET)**

**BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE**

**REGD Auto Consultant-SAE, Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.