

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	INCOME INSURAN	ICE LTD	Ref:	CS3/INC22008150/Rqy3e2	
	73 BRAS BASAH F #05-01 NTUC TRA 189556	ROAD DE UNION HOUSESINGAPORE	Date:	15/09/2022	
	ATTN: CHARLOTT	E CHEW	Code:	INC	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	FBQ 1990Y	Veh. Inspected	SJT 3166L	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	MT/1185553-002	Excess (\$)	0.00	
	Assign From	ANNIE KOH	Assign Date	24/08/2022	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA COROLLA ALTIS CL 1.6	c.c	1598	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	MR053REH104546296	Colour	GREY	
	Odometer	277267 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	205/55 R16	GRENLANDER	6 mm	
	L/H Front Tyre	205/55 R16	GRENLANDER	6 mm	
	R/H Rear Tyre	205/55 R16	GRENLANDER	6 mm	
	L/H Rear Tyre	205/55 R16	GRENLANDER	6 mm	
4.	4. Description of Damages				
	THE VEHICLE SUS	STAINED DAMAGES AT THE N/S			
5.		General Information			
	Accident Date	21/08/2022	Inspect Date / Time	24/08/2022 ( 11:41 AM )	
	Survey held at	MILLION AUTO SERVICE			
		4 PENJURU PLACE #01-12 2.8 PENJURU TECH HUP SINGAPORE 608782			
5a.	. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/INC22008150/Rqy3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

**Automotive Assessor** 

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser