

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE PTE LTD		Ref:	CS3/ASM22002660/Ety3e2	
	8 SHENTON WAY TOWERSINGAPOR	-	Date:	04/04/2022	
	ATTN: NG STACE	Y	Code	: ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHA 6792H	Veh. Inspected	FBK 8373P	
	Policy No.	VFX/P2419138	Coverage (\$)	0.00	
	Claim No.	S2M03VXY	Excess (\$)	0.00	
	Assign From	NG STACEY	Assign Date	22/03/2022	
2.	. Vehicle Particulars & Condition				
	Make & Model	HONDA CB400	c.c	399	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	NC421605015	Colour	BLACK	
	Odometer	-	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	120/60-17	GOODYEAR	4 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	160/60-17	GOODYEAR	4 mm	
	L/H Rear Tyre			mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY.				
5.	General Information				
	Accident Date	14/03/2022	Inspect Date / Time	23/03/2022 (03:13 PM)	
	Survey held at	I-MOTORING CREDIT PTE LTD			
	BLK 1008 BUKIT MERAH LANE 3 #01-14 SINGAPORE 159722				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000				
5b. Estimate Days of Repair					
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days			

Report Ref No. CS3/ASM22002660/Ety3e2

Inspected By

CHEN TSUE YEE

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser