

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22008156/ANCE2**Date:** 22/11/2022REFERENCE

Insured/Claimant:	LOO HUAN LIONG	Policy No:	1900233479	
Date of Loss:	18/08/2022	Nature of Claim:	OD	Claim No: 2211561079SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ241C		
Make & Model:	AUDI A3, 999cc SEDAN TFSI S TRONIC (LED) (A)	Engine No:	CHZC34871
Reg. Date:	25/10/2019 (Man. Year: 2019)	Chassis No:	WAUZZZ8V9LA007106
Colour:	White	Odometer:	26270 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$110,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,874.00	2,806.32	7,067.68	71.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,352.00	3,172.00	7,180.00	69.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,226.00	5,978.32	14,247.68	70.44
- Excess (S\$)	550.00	550.00	0.00	0.00
(S\$)	19,676.00	5,428.32	14,247.68	72.41
+ GST 7.00/7.00% (S\$)	1,377.32	379.98	997.34	72.41
Nett Amount (S\$)	21,053.32	5,808.30	15,245.02	72.41

INSPECTION

Date of Assignment:	25/08/2022	
Date Inspected:	24/08/2022	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER-RH	Repair	954.00 FS	*- FS
2	1		*FRONT DOOR-RH	Dented	3,265.00 FS	*2,612.00 FS
3	1		*FRONT OUTER DOOR SEAL-RH	Necessary	179.00 FS	*142.80 FS
4	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
5	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
6	1		*APPLICATOR	Not Necessary	9.00 FS	*- FS
7	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	252.00 FS	*- FS
8	1		*FRONT DOOR CATCH-RH	Not Necessary	116.00 FS	*- FS
9	1		*FRONT TYRE PRESSURE DATA PLATE	Necessary	34.00 FS	*26.96 FS
10	1		*FRONT WINDOW SLOT SEAL TRIM STRIP-RH	Not Necessary	346.00 FS	*- FS
11	1		*REAR DOOR-RH	Repair	3,265.00 FS	*- FS
12	1		*REAR OUTER DOOR SEAL-RH	Not Necessary	179.00 FS	*- FS
13	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
14	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
15	1		*APPLICATOR	Not Necessary	9.00 FS	*- FS
16	1		*REAR DOOR CATCH-RH	Not Necessary	105.00 FS	*- FS
17	1		*REAR WINDOW SLOT SEAL TRIM STRIP-RH	Not Necessary	331.00 FS	*- FS
18	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
19	1		*SUNDRIES	Necessary	400.00 FS	*24.56 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	9,874.00	2,806.32
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES	New	800.00	280.00
3	TO DISMANTLE AND REINSTALL FRONT BUMPER.TO RENEW RHS FRONT FENDER AND RHS FRONT DOOR AND RHS REAR DOOR.TO REPAIR RHS SILL PANEL.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	4,500.00	500.00
4	TO RESPRAY RHS FRONT FENDER,RHS FRONT DOOR,RHS REAR DOOR,RHS SILL PANEL AND RHS WING MIRROR COVER	New	4,500.00	2,200.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			10,352.00	3,172.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >