

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22008157/AQCM4**Date:** 23/11/2022**REFERENCE**

Insured/Claimant:	KON WEI SHENG	Policy No:	7220054902	
Date of Loss:	08/08/2022	Nature of Claim:	OD	Claim No: 7651840273SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNF3497H		
Make & Model:	AUDI A3 SPORTBACK, 1.5 TFSI S TRONIC (A)	Engine No:	DFY308671
Reg. Date:	23/05/2022 (Man. Year: 2021)	Chassis No:	WAUZZZGY1NA027039
Colour:	Black	Odometer:	5838 km
Engine Capacity:	1498 cc		
Market Value/New Car Price:	S\$165,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,572.00	2,756.80	13,815.20	83.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,972.00	1,722.00	2,250.00	56.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	20,544.00	4,478.80	16,065.20	78.20
- Excess (\$\$)	800.00	800.00	0.00	0.00
(\$\$)	19,744.00	3,678.80	16,065.20	81.37
+ GST 7.00/7.00% (\$\$)	1,382.08	257.52	1,124.56	81.37
Nett Amount (\$\$)	21,126.08	3,936.32	17,189.76	81.37

INSPECTION

Date of Assignment:	25/08/2022	
Date Inspected:	24/08/2022	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,677.00 FS	*1,341.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	290.00 FS	*- FS
3	2		*FRONT BUMPER CLOSING ELEMENT - LH / RH	Not Necessary	260.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - LOWER CENTRE	Cracked	433.00 FS	*346.00 FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	265.00 FS	*- FS
6	2		*FRONT BUMPER AIR GUIDE - LH / RH	Not Necessary	134.00 FS	*- FS
7	1		*FRONT BUMPER SPOILER	Not Necessary	326.00 FS	*- FS
8	2		*FRONT BUMPER TRIM COVER - LH / RH	Not Necessary	208.00 FS	*- FS
9	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	342.00 FS	*- FS
10	2		*FRONT BUMPER SENSOR SUPPORT - LH / RH	Not Necessary	86.00 FS	*- FS
11	1		*RADIATOR GRILLE	Cracked	932.00 FS	*745.60 FS
12	1		*RADIATOR GRILLE CLOSING ELEMENT - CENTER	Cracked	210.00 FS	*168.00 FS
13	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	120.00 FS	*95.60 FS
14	1		*FRONT BUMPER CARRIER	Not Necessary	748.00 FS	*- FS
15	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Not Necessary	108.00 FS	*- FS
16	1		*RADIATOR SUPPORT BRACKET	Not Necessary	93.00 FS	*- FS
17	1		*CAUTION SIGN STICKER	Not Necessary	16.00 FS	*- FS
18	1		*AIR CONDITIONER STICKER	Not Necessary	9.00 FS	*- FS
19	1		*HORN SIGNAL LOW TONE - LH	Not Necessary	154.00 FS	*- FS
20	1		*HORN SIGNAL HIGH TONE - RH	Not Necessary	162.00 FS	*- FS
21	4		*HORN BRACKET	Not Necessary	107.00 FS	*- FS
22	2		*HORN BRACKET UPPER - LH / RH	Not Necessary	70.00 FS	*- FS
23	2		*FRONT PARKING AID SENSOR - INNER / OUTER	Not Necessary	558.00 FS	*- FS
24	4		*FRONT PARKING AID SEAL RING	Not Necessary	52.00 FS	*- FS
25	2		*HEADLIGHT - LH / RH	Not Necessary	8,168.00 FS	*- FS
26	2		*HEADLIGHT LIFT CYLINDER - LH / RH	Not Necessary	422.00 FS	*- FS
27	1		*HEADLIGHT HOSE	Not Necessary	108.00 FS	*- FS
28	1		*RADIATOR AIR GUIDE SEAL - RH	Not Necessary	14.00 FS	*- FS
29	2		*FRONT AIR GUIDE - LH / RH	Not Necessary	84.00 FS	*- FS
30	1		*OUTSIDE TEMPERATURE SENSOR HOLDER	Not Necessary	6.00 FS	*- FS
31	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
32	1		*SUNDRIES	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 16,572.00 2,756.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	800.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
4	TO RESPRAY FRONT BUMPER	New	1,200.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	192.00
Gross Labour Cost (\$\$)			3,972.00	1,722.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >