

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22008159/RNCE2**Date:** 23/11/2022REFERENCE

Insured/Claimant: LOH KOI LEE Policy No: 2070067312-02
Date of Loss: 12/08/2022 Nature of Claim: OD Claim No: 3838282354SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFS2221U**
Make & Model: AUDI A3, 1.4 SEDAN TFSI (AMBIENTE) (A) Engine No: CXS095851
Reg. Date: 30/05/2014 (Man. Year: 2014) Chassis No: WAUZZZ8V2E1037180
Colour: Black Odometer: 105147 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$41,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,501.00	12,162.96	8,338.04	40.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,274.00	8,274.00	6,000.00	42.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	34,775.00	20,436.96	14,338.04	41.23
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	34,175.00	19,836.96	14,338.04	41.95
+ GST 7.00/7.00% (S\$)	2,392.25	1,388.59	1,003.66	41.95
Nett Amount (S\$)	36,567.25	21,225.55	15,341.70	41.95

INSPECTION

Date of Assignment: 25/08/2022
Date Inspected: 24/08/2022 Inspected At: 24 Benoi Sector Singapore 629857
Estimated Period of Repair: 10.0 days Repairer: Premium Automobiles Pte Ltd

Adjuster: MOHD RASUL**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,377.00 FS	*1,901.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	195.00 FS	*- FS
3	1		*FRONT BUMPER TRIM COVER - RH	Deformed	182.00 FS	*145.20 FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	175.00 FS	*- FS
5	1		*FRONT BUMPER PULL STRAP LOWER (4PCS)	Cracked (3Pcs Only)	231.00 FS	*138.48 FS
6	1		*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	43.00 FS	*- FS
7	1		*RADIATOR AIR GUIDE GRILLE - RH	Missing	122.00 FS	*97.20 FS
8	1		*RADIATOR GRILLE	Cracked	765.00 FS	*612.00 FS
9	1		*RADIATOR GRILLE COVER	Cracked	109.00 FS	*87.20 FS
10	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	847.00 FS	*- FS
11	1		*FRONT BUMPER FOAM FILLER PIECE	Torn	154.00 FS	*122.80 FS
12	1		*FRONT BUMPER REINFORCEMENT BEAM COVER	Distorted	63.00 FS	*49.84 FS
13	1		*HORN SIGNAL HIGH TONE - RH	Not Necessary	213.00 FS	*- FS
14	1		*FRONT FENDER - RH	Bent	954.00 FS	*763.20 FS
15	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	75.00 FS	*- FS
16	1		*FRONT FENDER BRACET	Necessary	46.00 FS	*36.40 FS
17	6		*FRONT FENDER RIVET	Necessary	23.00 FS	*18.24 FS
18	1		*FRONT FENDER BRACE	Dented	107.00 FS	*85.60 FS
19	1		*FRONT FENDER BRACKET - RH	Bent	31.00 FS	*24.24 FS
20	1		*FRONT WHEEL HOUSING LINER - RH	Not Necessary	183.00 FS	*- FS
21	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	93.00 FS	*- FS
22	1		*BONNET	Buckled	3,348.00 FS	*2,678.40 FS
23	1		*BONNET ATTACHMENT PARTS	Not Necessary	172.00 FS	*- FS
24	2		*BONNET HINGE - LH / RH	Bent	136.00 FS	*108.48 FS
25	1		*FRONT BONNET EDGE PROTECTION	Necessary	31.00 FS	*24.72 FS
26	1		*BONNET GAS FILLED STRUT	Damaged	110.00 FS	*88.00 FS
27	1		*BONNET STRIKER	Not Necessary	123.00 FS	*- FS
28	1		*BONNET LOCK	Bent	228.00 FS	*182.00 FS
29	1		*BONNET CATCH HOOK	Bent	71.00 FS	*56.32 FS
30	1		*BONNET CATCH HOOK	Not Necessary	100.00 FS	*- FS
31	1		*BONNET BOWDEN CABLE	Not Necessary	64.00 FS	*- FS
32	1		*BONNET RELEASE CABLE COVER	Not Necessary	11.00 FS	*- FS
33	1		*HEADLIGHT - RH	Broken	2,810.00 FS	*2,248.00 FS
34	1		*HEADLIGHT POWER MODULE	Damaged	635.00 FS	*507.60 FS
35	1		*GAS DISCHARGE LAMP	Not Necessary	454.00 FS	*- FS
36	1		*HEADLIGHT CONTROL UNIT	Damaged	1,279.00 FS	*1,023.20 FS
37	1		*HEADLIGHT HOSE - RH	Not Necessary	60.00 FS	*- FS
38	1		*LIFT CYLINDER - RH	Not Necessary	211.00 FS	*- FS
39	1		*LIFT CYLINDER HOSE	Not Necessary	204.00 FS	*- FS
40	1		*LOCK CARRIER	Cracked	806.00 FS	*644.80 FS
41	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Damaged	21.00 FS	*16.32 FS
42	6		*READY-MIX COOLANT	Necessary	297.00 FS	*237.12 FS
43	1		*RADIATOR AIR GUIDE - RH	Deformed	28.00 FS	*22.16 FS
44	1		*RADIATOR AIR GUIDE OUTER SEAL - RH	Not Necessary	9.00 FS	*- FS
45	1		*RADIATOR AIR GUIDE UPPER CENTRE	Not Necessary	14.00 FS	*- FS
46	1		*A/C CONDENSER	Not Necessary	570.00 FS	*- FS
47	1		*FRONT WINDOW SLOT SEAL TRIM STRIP - RH	Not Necessary	346.00 FS	*- FS
48	1		*FRONT WINDOW GUIDE TRIM STRIP - RH	Not Necessary	287.00 FS	*- FS
49	1		*FRONT WINDOW WATER DEFLECTOR STRIP - RH	Not Necessary	104.00 FS	*- FS
50	1		*FRONT NO PLATE	Bent	60.00 FS	*60.00 FS
51	1		*SUNDRIES	Necessary	700.00 FS	*5.60 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*PLENUM CHAMBER COVER (Supplementary)	Broken	199.00 FS	*159.20 FS
53	1		*STICKER FOR AIR CONDITIONER (Supplementary)	Necessary	9.00 FS	*6.64 FS
54	1		*SIGN CAUTION STICKER (Supplementary)	Necessary	16.00 FS	*12.40 FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	20,501.00 12,162.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS FOR R1234	New	1,500.00	1,500.00
4	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR	New	380.00	280.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,600.00	2,750.00
6	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, BONNET, HINGES, RHS UPPER A-PILLAR AND RHS FRONT DOOR	New	5,000.00	2,200.00
7	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	484.00	384.00
8	TO RESPRAY LHS FRONT FENDER (Supplementary)	New	550.00	550.00
Gross Labour Cost (\$\$)			14,274.00	8,274.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >