



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 1330R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER COVER	TO REPAIR SEE LABOUR	591.75	-
1	FRONT BUMPER BRACKET LH	NOT NECESSARY	77.00	-
10	FRONT BUMPER CLIPS @\$2.20	NOT NECESSARY	22.00	-
1	FRONT BUMPER TOW COVER	NOT NECESSARY	86.50	-
1	FRONT BUMPER MOULDING LH	CUT	172.50	172.50
1	FRONT BUMPER CENTRE LOWER GRILLE	SCRATCHED	301.90	301.90
	LESS 25% DISCOUNT		-312.91	-118.60
			938.74	355.80
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT BUMPER COVER.		550.00	350.00
	SPRAY PAINTING.		300.00	250.00
	TUFF COAT.	NOT NECESSARY	60.00	-
	CHECK LIGHTING.	NOT NECESSARY	60.00	-
			970.00	600.00
	GRAND TOTAL		1,908.74	955.80
	RECOMMENDED COST OF REPAIRS (CONFIRMED)			955.80

Report Ref No. NS/INC22008187/Gvcm4

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.